

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B 10419</b>
7. Unit Agreement Name <b>S. Caprock Queen</b>
8. Farm or Lease Name <b>S. Caprock Queen</b>
9. Well No. <b>T-25, W-4, Sec. 20</b>
10. Field and Pool, or Wildcat <b>S. C aprock Queen</b>
12. County <b>Chaves</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator <b>Union Oil of California</b>
3. Address of Operator <b>500 N. Marienfeld - Midland, Texas</b>
4. Location of Well UNIT LETTER <b>D</b> <b>660</b> FEET FROM THE <b>N</b> LINE AND <b>660</b> FEET FROM <b>W</b> <b>20</b> <b>15 S</b> <b>31 E</b> THE LINE, SECTION TOWNSHIP RANGE NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>GL 4427</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

## Plugging Procedures Below:



1. 13 3/8" @ 327' Circ.
2. 5 1/2" @ 3101' W/150 Sx.
3. Perf. Open Hole @ 3101' - 3120'

Plug #1 - 25 Sx. @ 3100'  
 Plug #2 - 25 Sx. @ 5 1/2" Stub  
 Plug #3 - 35 Sx. @ Base of Surface 327'  
 Plug #4 - 5 Sx. @ Surface

**Establish Dry Hole Marker**

**H. D. Oden, Inc.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE <b>Agent for Union Oil of California</b>	DATE <b>July 20, 1971</b>
APPROVED BY 	TITLE <b>SUPERVISOR DISTRICT I</b>	DATE <b>JUL 23 1971</b>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUL 22 1971

OIL CONSERVATION COMM.  
HOUSTON, TEXAS