

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

24
JUL 11 1971

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 20-064000 E-2771
7. Unit Agreement Name S. Caprock Queen Unit
8. Farm or Lease Name S. Caprock Queen Unit
9. Well No. 77-33
10. Field and Pool, or Wildcat S. Caprock Queen Unit
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	CHANGE OK <i>Al</i>
2. Name of Operator Union Oil of California	
3. Address of Operator 500 N. Marienfeld - Midland, Texas	
4. Location of Well UNIT LETTER K 1980 FEET FROM THE S LINE AND 1962 FEET FROM THE W LINE, SECTION 30 TOWNSHIP 15 S RANGE 31 E NMPM.	
15. Elevation (Show whether DE, RT, GR, etc.) GL 4447	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 9 5/8" @ 300'
2. 5 1/2" @ 3150' W/175 Gx.
3. Perf. @ 3143' - 3151'

Plug #1 - 100' Plug @ Perf.
Plug #2 - 100' Plug @ Stub of 5 1/2"
Plug #3 - 100' Plug in and out of Surface
Plug #4 - 20' Plug @ Surface

Establish Dry Hole Marker

H. D. Oden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

**Agent for Union Oil
of California**

SIGNATURE *H. D. Oden*

TITLE

DATE **June 30, 1971**

APPROVED BY *[Signature]*

TITLE **SUPERVISOR DISTRICT 1**

DATE **JUL 7 1971**