

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>LC 064900</b>
7. Unit Agreement Name <b>S. Caprock Green Unit</b>
8. Farm or Lease Name <b>S. Caprock Green Unit</b>
9. Well No. <b>T-48, W-16, Sec. 30</b>
10. Field and Pool, or Wildcat <b>S. Caprock Green Unit</b>
12. County <b>Chaves</b>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator <b>Union Oil of California</b>
3. Address of Operator <b>500 N. Marionfeld - Midland, Texas</b>
4. Location of Well UNIT LETTER <b>F</b> , <b>990</b> FEET FROM THE <b>S</b> LINE AND <b>990</b> FEET FROM THE <b>R 7</b> LINE, SECTION <b>1 30</b> TOWNSHIP <b>15 S</b> RANGE <b>31 E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>CL 4438</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 8 5/8" @ 300'
2. 5 1/2" @ 3200' W/175 Sec.
3. Perf. @ 3172' - 3184'

Plug #1 - 100' Plug @ Perf.  
Plug #2 - 100' Plug @ Stub of 5 1/2"  
Plug #3 - 100' Plug in and out of Surface  
Plug #4 - 20' Plug @ Surface

Establish Dry Hole Marker

H. D. Oden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. D. Oden TITLE Agent for Union Oil of California DATE June 30, 1971

APPROVED BY [Signature] TITLE SUPERVISOR DISTRICT I DATE JUL 7 1971

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 6 1971

OIL CONSERVATION COMM.  
HOBBS, N. M.