NO. OF COPIES RECEIVED		Form C-103
		Supersedes Old
		C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		5a. Indicate Type of Lease
u.s.g.s.	· 	State X Fee
LAND OFFICE		5. State Oil & Gas Lease No.
OPERATOR		B_8318
	DEM NOTICES AND DEDODES ON WELLS	
SUN (DO NOT USE THIS FORM FOR USE *APPLI	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. CATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL GAS WELL WELL	OTHER- Water Injection No.	wth Caprock Queen Unit 2
2. Name of Operator	action Company	Tract #9
Address of Operator	action Company	9. Well No.
B 0 Por 67	Loco Hills, New Mexico 88255	#1 10. Field and Pool, or Wildcat
4. Location of Well	1000 IIII of IIII	
¥	1980 FEET FROM THE South LINE AND 1980 FEET FRO	M Caprock Sysee
		<u> </u>
THE West LINE, SE	ECTION TOWNSHIP	
mmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4396 GL	Chaves
16.	ck Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
	F INTENTION TO: SUBSEQUEN	NT REPORT OF:
		ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	-
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
	COMMENCE ORILLING OPNS.  CHANGE PLANS  CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER	COMMENCE ORILLING OPNS.  CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER	PLUG AND ABANDONMENT
TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER	COMMENCE ORILLING OPNS.  CHANGE PLANS  CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
other  17. Describe Proposed or Complete work) SEE RULE 1103.  Intend to plug and  1. Pull tubin  2. Set cast i  3. Spot 25 fo  4. Set 10 sac  5. Set surface	commence Drilling OPNS.  CASING TEST AND CEMENT JOB  OTHER  ded Operations (Clearly state all pertinent details, and give pertinent dates, including and packer.  iron bridge plug at base of 42 liner approximately pot cement plug on top of bridge plug.  ck cement plug at surface.  ce marker.  l equipment and clean up location.	PLUG AND ABANDONMENT
other  17. Describe Proposed or Complete work) see Rule 1103.  Intend to plug and  1. Pull tubin  2. Set cast i  3. Spot 25 fo  4. Set 10 sac  5. Set surfac  6. Remove all  No casing will be	change plans  ch	ng estimated date of starting any propose  y 3010.
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER  17. Describe Proposed or Complete work) SEE RULE 1103.  Intend to plug and 1. Pull tubin 2. Set cast i 3. Spot 25 fo 4. Set 10 sac 5. Set surfac 6. Remove all No casing will be	commence or including of the pertinent details, and give pertinent dates, including and packer.  if abandon well as follows:  if abandon well as follows:  if and packer.  if aron bridge plug at base of the liner approximately on top of bridge plug.  if acceptance of the liner approximately on the properties of the plug.  If a properties of the liner approximately on the plug at surface.  If a pulled from well.  If the liner approximately on the plug at surface.  If a pulled from well.  If the liner approximately on the plug at surface.  If the liner approximately on the plug at surfa	ng estimated date of starting any propose  y 3010.  but Date Sept. 8, 1977
other  17. Describe Proposed or Complete work) see Rule 1103.  Intend to plug and  1. Pull tubin  2. Set cast i  3. Spot 25 fo  4. Set 10 sac  5. Set surfac  6. Remove all  No casing will be	commence or including of the pertinent details, and give pertinent dates, including and packer.  iron bridge plug at base of light liner approximately on top of bridge plug.  ck cement plug on top of bridge plug.  ck cement plug at surface.  ce marker.  l equipment and clean up location.  pulled from well.  District Superintenden	ng estimated date of starting any propose  y 3010.

APPROVED BY \_\_\_

## [ MENED

SIP 1 1971

OIL CLASERVATION-COMM.