

COPIES RECEIVED		
TRIBUTION		
FE		
E		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. B-10420	
7. Unit Agreement Name North Caprock Queen Unit 2	
8. Farm or Lease Name Tract#3	
9. Well No. 2	
10. Field and Pool, or Wildcat Caprock Queen	
12. County Chaves	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Water Injection</u>
2. Name of Operator <u>Anadarko Production Company</u>
3. Address of Operator <u>P. O. Box 647 Artesia, New Mexico 88210</u>
4. Location of Well UNIT LETTER <u>C</u> , <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>1</u> TOWNSHIP <u>13S</u> RANGE <u>31E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <u>4403 GL</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pumped 25 sacks cement at 3008'. Cut off oil string at 1125'. Pumped 25 sacks cement at casing cut off point. Pumped 25 sacks cement at base of surface casing 10 sacks at surface with heavy mud between all plugs. Set surface marker and cleaned up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>L. R. Murray, Jr.</u>	TITLE <u>Agent</u>	DATE <u>5/10/74</u>
APPROVED BY <u>John W. Pungzon</u>	TITLE <u>Geologist</u>	DATE <u>5/10/74</u>
CONDITIONS OF APPROVAL, IF ANY:		