

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

JUN 5 11 34 AM '68

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	B-9541

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Water injection well</b>	7. Unit Agreement Name <b>Pebble Queen</b>
2. Name of Operator <b>Great Western Drilling Company</b>	8. Farm or Lease Name <b>State 33</b>
3. Address of Operator <b>P. O. Box 1659, Midland, Texas 79701</b>	9. Well No. <b>16</b>
4. Location of Well UNIT LETTER <b>F</b> , <b>1980</b> FEET FROM THE <b>North</b> LINE AND <b>1980</b> FEET FROM THE <b>West</b> LINE, SECTION <b>2</b> TOWNSHIP <b>13-S</b> RANGE <b>31-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Caprock Queen</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4406 GR</b>	12. County <b>Chaves</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This unit was terminated June 1, 1968. We plan to place a 25 sack cement plug across the open hole 3038-3018 and 140' into 4½". Pull about 800' of 4½", and spot 25 sacks into the stub. Place 25 sacks at the shoe of the surface pipe 8 5/8 @ 286 with 10 sacks at the surface.

A proper marker and clean-up will be made.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>O. H. Crews</u>	TITLE <u>Administrative Coordinator</u>	DATE <u>June 4, 1968</u>
APPROVED BY <u>[Signature]</u>	TITLE <u></u>	DATE <u></u>

CONDITIONS OF APPROVAL, IF ANY:

Min. 1 between plugs