

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-11447	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection		7. Unit Agreement Name
2. Name of Operator		North Caprock unit
3. Address of Operator		8. Field or Lease Name
Armadillo Production Company		Tract 25
4. Location of Well		9. Well No.
P. O. Box 117 Artesia, New Mexico 88210		2
UNIT LETTER H FEET FROM THE North LINE AND 660 FEET FROM		10. Field and Pool, or Wildcat
THE East LINE, SECTION 11 TOWNSHIP 13 RANGE 21 N.M.P.M.		Caprock unit
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4405 GL		Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set Abandonment plug at 3010; pumped 35' cement on top of plug. Shot off 1 string at 890'; pumped 30 sacks cement from 790' to 890'; pumped 40 sacks cement from 210' to 310'; 10 sacks cement at surface with heavy mud between all plugs. Set surface marker and cleaned up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>E. D. Murray, Jr.</i>	TITLE Agent	DATE 5/20/74
APPROVED BY <i>John W. Runyan</i>	TITLE Geologist	DATE OCT 7 1974
CONDITIONS OF APPROVAL, IF ANY:		