PEBBLE OUEEN #3

8/10/93 RUPU. Picked up tubing, ran with notched collar on bottom. Hit bad place in casing @ approx. 1280'. Worked tubing thru, tagged out @ 3019'. Broke circ., spotted 50 sxs. plug, Class "C" neet. Tried to tag after 3 1/2 hrs., could not find hard cement. Spotted 50 sxs. more Class "C" neet @ TD. Pulled tubing above cement.

8/11/93 Tagged plug @ 2663', mudded up to 1200'. Set 20 sxs. plug, with 3% CaCl2 @ 1200'. Tagged in 2 1/2 hrs. Tagged @ 1180' solid, broke circulation. Set 25 sxs. 3% CaCl2 @ 1180' plug, could not tag in 2 1/2 hrs., went thru plug. Pulled tubing above cement.

8/12/93 Tagged plug @ 975'. Spotted mud up to 362'. Set 25 sxs. plug @ 362', mudded up to surface. Set 60' plug to surface.

Witnessed by Jack Griffin, NMOCD.