| COPIES RECEIVED   TRIBUTION   TFE   LE   U.S.G.S.   | NEW MEXICO OIL CONSERVATION COMMISSION |                    | Form C-103<br>Supersedes Old<br>C-102 and C-103<br>Effective 1-1-65 |
|---|--|--------------------|---|
|   | 4                                      |                    | State X Fee   |
| OPERATOR  | 1                                      |                    | 5. State Oil & Gas Lease No.  |
|   |  |                    | B-9155  |
| SUNDRY NOTICES AND REPORTS ON WELLS<br>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.<br>USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.) |  |                    |   |
| 1.<br>OIL GAS WELL WELL   | OTHER- Water Inject                    |                    | 7. Unit Acceement Name<br>North Caprock Jueen<br>Unit 2             |
| 2. Name of Operator   |  |                    | 8. Farm or Lease Name   |
| Anadarko Production Company   |  |                    | Tract ##  |
|   |  |                    | 9, Well No.   |
| P. O. Box 647 Artesia, Ndw Mexico 88210   |  |                    | 2<br>10. Field and Pool, or Wildcat                                 |
| UNIT LETTER K 1980 FEET FROM THE South LINE AND 1980 FEET FROM  |  |                    | • • • •   |
| UNIT LETTER   | FEET FROM THE DOUGL                    | LINE AND FEET FROM |   |
| THE West LINE, SECTION 12 TOWNSHIP 13 S RANGE 31 E NMPM.  |  |                    |   |
| 15. Elevation (Show whether DF, RT, GR, etc.)   |  |                    | 12. County  |
| AIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII  |  |                    | Chaves  |
| 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  |  |                    |   |
|   |  |                    | T REPORT OF:  |
| PERFORM REMEDIAL WORK   | PLUG AND ABANDON                       | REMEDIAL WORK      | ALTERING CASING   |
| 0THER   |  | OTHER              | X   |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set abandonment plug at 3020'. Pumped 35' cement on top of plug. Shot off oil string at 951'. Pumped 30 sacks cement from 900' to 1000'. Pumped 40 sacks cement from 210' to 310'; 10 sacks cement at surface with heavy mud between all plugs. Set surface marker and cleaned up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED A. Mucucay, J.V. TITLE Agent DATE 5/10/74 APPROVED BY John W. Munyan TITLE DATE DATE TITLE