

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Mar 8 11 32 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B - 10424	
7. Unit Agreement Name	
North Central Caprock	
Queen Unit 13	
8. Farm or Lease Name	
9. Well No.	
S-13 #6	
10. Field and Pool, or Wildcat	
Caprock Queen	
12. County	
Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- Injection Well
2. Name of Operator		
Great Western Drilling Company		
3. Address of Operator		
Box 1659, Midland, Texas		
4. Location of Well		
UNIT LETTER F , 1980 FEET FROM THE North LINE AND 1980 FEET FROM		
THE West LINE, SECTION 1e 13 TOWNSHIP 1e-S 13 RANGE e 31-E NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		
4421 D.F.		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been an injection well since May, 1960 having had 507,826 barrels of water injected. Great Western Drilling Company plans to set a 25 sacks plug in the 5-1/2" casing, above the perforations, (3050 - 2875), cut and pull some 1000' of 5-1/2" casing, place a 25 sack plug in the stub, 25 sacks at the shoe of the surface casing with 5 sacks at the surface. (The hole will be loaded with mud before this work is started. A proper cleanup and marker will be made. Starting date as soon as possible.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED O.H. Crews TITLE Administrative Coordinator DATE March 7, 1966

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

16