Form 9-331 (May 1963)	UNITED S DEPARTME, OF GEOLOGICAI	THE INTERI		N TRIPLICATE* tructions re-	5. LEASE DESIGNATION	eau No. 42-R1424.	
	DRY NOTICES AND form for proposals to drill or t Use "APPLICATION FOR PER		ack to a uternet	refervoir.	6. IF INDÍAN, ALLOTT		
OIL GAS WELL OTHER 2. NAME OF OPERATOR					7. UNIT AGREEMENT NAME North Central Ceprock 8. FARM OB LEASE NAME		
3. ADDRESS OF OPERATOR	Western Drilling Co	apany	<u> </u>		9. WELL NO.		
P.O. Box 1659 Midland, Texas LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' from jouth Line and 660' from East Line of Section 15					10. FIELD AND POOL, OR WILDCAT Caprock Queen 11. SBC., T., R., M., OR BLK. AND SURVEY OR AREA		
				Section 13	15, 13-8, 31-	·E	
14. PERMIT NO.	15. ELEVATIONS	(Show whether DF,	RT, GR, etc.)		12. COUNTY OR PARIS	H 13. STATE	
1.0		4421GR			Chaves	New Mexico	
16.	Check Appropriate Box	To Indicate N	ature of Notice				
1	NOTICE OF INTENTION TO:	[ <sup></sup> ]		SUBSEQU:	ENT REPORT OF:	<b>[</b> ]	
TEST WATER SHUT-O	[]		WATER SHI		REPAIRING		
FRACTURE TREAT SHOOT OR ACIDIZE	ABANDON*	6 18 18		DR ACIDIZING	ALTERING ( ABANDONMI		
REPAIR WELL	CHANGE PLANS		(Other)	OR ACIDIZING	ABANDON MI	-X-	
(Other)			(Nor	: Report results	of multiple completion tion Report and Log for	OB Well	
sacks @30	s shot and pulled @ O', and 10 sacks at eanup and proper ma	the surfac	:•.	·			
	PRODUCE ARESER					·	
signed <u>E46</u>	the foregoing is true and correct		<b>inis</b> trativ	• Coordina	LOT DATE5	-4-65	
(This space for Feder	al or State office use)						
APPROVED BY CONDITIONS OF AF		TITLE		100.TZ	231965		
	*	See Instructions	on Reverse Si	le BF	SHOEER FL		