

OF COPIES RECEIVED	
DISTRIBUTION	
SAN TA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

30-005-00829

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- WATER INJECTION WELL	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator GREAT WESTERN DRILLING COMPANY	5. State Oil & Gas Lease No. E-7659
3. Address of Operator P. O. BOX 1659 MIDLAND TX 79701	7. Unit Agreement Name ROCK QUEEN UNIT 23
4. Location of Well UNIT LETTER N 660 FEET FROM THE SOUTH LINE AND 1980 FEET FROM THE WEST LINE, SECTION 23 TOWNSHIP 13-S RANGE 31-E NMPM.	8. Farm or Lease Name TRACT NO. 33
	9. Well No. 29-14
	10. Field and Pool, or Wildcat CAPROCK QUEEN
15. Elevation (Show whether DF, RT, GR, etc.) GR 4413'	12. County CHAVES

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMOCC notified 24 hours prior to setting bottom plug.

2-6-76 RU csg pullers. Ran tbg to 1797'. Could not penetrate deeper. Pulled tbg. Ran taper tbg sub. Worked tbg from 1797'-1827'. Pulled tbg.
2-7-76 Reran tbg w/tapered sub, tagged plug @ 1827'. Jarred and worked on plug without success. Pulled tbg. RD csg pullers.
2-9-76 RU PU & Rev. unit. Ran 3-3/4" bit w/4-DC on 2" tbg. Tagged plug @ 1827'. Drld & pushed plug to 1835'. Rec. rubber, metal shavings, cuttings & busted bit cones. Pulled drilling string, left 1 cone in hole.
2-10-76 Made 3 runs w/magnet, rec. steel shavings & small pieces of tbg. Ran new 3-7/8" bit, 4-3-1/8" DC & tbg. Drld 1835'-1840' in 7 hrs. Rec. steel shav. & cutt.
2-11-76 Drld 3/4 hr on junk, made 3". Pull bit. Ran magnet, rec. steel cuttings. Ran lead impress. block. Bottom of block not marked, but sides were scored. Ran tbg opened ended & tagged bottom @ 1840'. POH. Ran bit, DC & tbg. Drld 2' to 1840', in 4 hrs. Rec. steel shavings & small pieces of pipe.
2-12-76 Drld on junk 2 hrs. @ 1840' no progress. POH. Ran 3-7/8x2-3/4 Kutrite shoe, 2 jts WP & 4 DC. WO 6' & WP plugged. POH. Rec. 6'-of spirally coiled csg. & small pieces of junk. WIH/3-7/8" bit & 6 DC. Drld on junk for 2 hrs @ 1847', no progress. POH. Ran 3 1/2" lead impress. block. Impress. showed pointed junk looking up. - Cont'd on back

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 25. Ballard TITLE General Superintendent DATE 2-18-76

APPROVED BY 1076 DATE 1076
CONDITIONS OF APPROVAL, IF ANY: