

OF COPIES RECEIVED		
DISTRIBUTION		
SANITAFE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

30-005-00840

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- WATER INJECTION WELL	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator GREAT WESTERN DRILLING COMPANY	5. State Oil & Gas Lease No. B-9359
3. Address of Operator P. O. BOX 1659, MIDLAND TX 79701	7. Unit Agreement Name ROCK QUEEN UNIT 34
4. Location of Well UNIT LETTER N, 1980 FEET FROM THE WEST LINE AND 660 FEET FROM THE SOUTH LINE, SECTION 24 TOWNSHIP 13-S RANGE 31-E NMPM.	8. Farm or Lease Name TRACT NO. 10
15. Elevation (Show whether DF, RT, GR, etc.) GR 4407'	9. Well No. 24-14
	10. Field and Pool, or Wildcat CAPROCK QUEEN
	12. County CHAVES

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMOCC Notified 24 hours prior to setting bottom plug.

1-27-76 Rigged up csg. pullers.

1-28-76 Ran tbq & tagged bottom @ 3020'. Spotted 25 sx plug 3020'-2805'. Pulled 30 jts. tbq. WOC 2 hrs. Ran wireline meas. to 3020' - found no plug. Reran tbq to 3020' WOC 2 more hrs. Spotted 2nd 25 sx plug 3020'-2805'.

1-29-76 Ran wireline meas. to 3020' - found no plug. Reran tbq to 3020'. Spotted 3rd 25 sx plug. Pulled tbq. WOC 2 hrs. Reran tbq & tagged plug @ 2990'(30' plug). Spotted 4th 25 sx plug from 2990'-2775'. Pulled tbq.

1-30-76 Ran tbq & tagged plug @ 2753' (237' of fill on plug #4). Displaced hole w/9½#brine gelled mud. Pulled tbq. Rigged up csg. jacks. Stretched csg., shot csg @ 1305' would not come. Reshot @ 1139'. Pulled & rec. 2 36 jts, 5½" 14#/ft. J-55 csg. (1145.72') which was not in good shape. Set 20 sx plug 1195'-1095'. Set 30 sx p plug 338'-236'. Pulled tbq.

1-31-76 Set 10 sx plug @ surface w/dry hole marker. P & A 1-31-76.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 2h. Ballard TITLE General Superintendent DATE 2-3-76

APPROVED BY _____ TITLE _____ DATE NOV 5 1976

CONDITIONS OF APPROVAL, IF ANY: