

COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-5663

30-005-00846

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- WATER INJECTION WELL	7. Unit Agreement Name ROCK QUEEN UNIT 24
2. Name of Operator GREAT WESTERN DRILLING COMPANY	8. Farm or Lease Name TRACT NO. 26
3. Address of Operator P. O. BOX 1659 MIDLAND TX 79701	9. Well No. 24-16
4. Location of Well UNIT LETTER P 330 FEET FROM THE SOUTH LINE AND 990 FEET FROM THE EAST LINE, SECTION 24 TOWNSHIP 13-S RANGE 31-E NMPM.	10. Field and Pool, or Wildcat CAPROCK QUEEN
11. Elevation (Show whether DF, RT, GR, etc.) GR 4393'	12. County CHAVES

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1-22-76 Rigged up csg. pullers. Ran tbq & set 25 sx cmt plug 3048'-2725'. Witness by Mr. Nathan Klegg, NMOCC. Pulled tbq.
- 1-23-76 Ran tbq & tagged plug @ 3046' (2' fill). Re-cemented w/25 sx 3046'-2723'. Pulled tbq. Ran wireline measurement & tagged top of cmt @ 2594'. Ran tbq & spotted 15 sx plug 1525'-1331'. Pull tbq., rigged up csg jacks. Worked & stretched csg. Shot csg @ 1203' & would not come. Re-shot csg @ 1014' & worked pipe free. Pulled & recovered 55 jts of 4 1/2" csg. (1014' csg-wireline meas. Not witnessed by NMOCC.
- 1-24-76 Ran tbq. Mixed mud w/10# brine & 25#/bbl. brine gel & spotted 20 sx plug 1064-958'. Spotted 30 sx plug 201'-99'. Spotted 10sx plug @ surface w/dry hole marker. Plugging not witnessed by NMOCC.

PLUGGED AND ABANDONED 1-24-76.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>2. L. Ballard</u>	TITLE <u>General Superintendent</u>	DATE <u>1-26-76</u>
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

NOV 5 1976