

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 South First, Artesia, NM 88210
 District III
 1030 Rio Brazos Rd., Aztec, NM 87410
 District IV
 2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 2040 South Pacheco
 Santa Fe, NM 87505

WELL API NO.
30-005-00880

5. Indicate Type of Lease
 STATE FEE

6. State Oil & Gas Lease No.
B-10418-75

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well Gas Well Other INJECTION

2. Name of Operator
QUEEN SAND OPERATING CO.

3. Address of Operator
13760 NOEL RD. SUITE 1030 LB 44 DALLAS TX. 75240

4. Well Location
 Unit Letter D : 660 feet from the NORTH line and 660 feet from the WEST line
 Section 16 Township 13S Range 31E NMPM County CHAVEZ

7. Lease Name or Unit Agreement Name:
ROCK QUEEN UNIT

8. Well No.
38

9. Pool name or Wildcat
CAPROCK QUEEN

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
4425' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
FULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. 11-4-00 SET 5 1/2" CIBP @ 2950' SPOT 25 SX'S "C" CMT @ 2950' WOC - TAG @ 2720'
2. 11-4-00 DISPL. HOLE WITH PLUG MUD 25# GEL PER BBL 10# B.W.
3. 11-4-00 PERF @ 1450' & SQZ 75 SX'S "C" CMT. WOC. TAG @ 1380' ON 11-5-00
4. 11-5-00 PERF @ 310' & SQZ 75 SX'S "C" CMT. WOC - TAG @ 200'
5. 11-5-00 SPOT 10 SX'S "C" CMT FROM 50' - SURF
6. 11-5-00 CUT OFF WELLHEADS & WELD ON CAP
7. 11-5-00 INSTALL DRY HOLE MARKER DATED 11-5-00
8. 11-5-00 MOVE OFF P&A EQUIP

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE MANAGER DATE 11-6-00
 Type or print name JIMMY BAGLEY Telephone No. (915) 683-4996
 (This space for State use)
 APPROVED BY [Signature] TITLE _____ DATE _____
 Conditions of approval, if any:

TR-5 BWW