

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SUBMIT IN TRIPLICATE
ORIGINAL COPY ON REVERSE SIDEForm approved
Budget Bureau No. 42 R1424
5. LEASE DESIGNATION AND SERIAL NO.
NM 03844
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER WATER INJECTION WELL	7. UNIT AGREEMENT NAME ROCK QUEEN UNIT
2. NAME OF OPERATOR GREAT WESTERN DRILLING COMPANY 30-005-00884	8. FARM OR LEASE NAME TRACT NO. 4
3. ADDRESS OF OPERATOR P. O. BOX 1659 MIDLAND TX 79701	9. WELL NO. -8
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit No. H 1980'FNL 330'FEL, Sec. 27, T-13-S, R-31-E	10. FIELD AND POOL, OR WILDCAT CAPROCK QUEEN
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SECTION 27
15. ELEVATIONS (Show whether DF, RT, GR, etc.) DF 4411'	12. COUNTY OR PARISH CHAVES
	13. STATE NEW MEXICO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

USGS notified 24 hrs. prior to setting bottom plug.

- 3/1/76 RU csg pullers. Dropped top rubber plug in csg. Pushed plug 20', would not go further. Backed off top 2 jts csg & removed plug. Reran 2 jts csg & screwed back into csg. Ran tbg, tagged bottom @ 2994'. Spotted 25 sx plug @ 2994'.
- 3/3/76 Ran wireline meas. & tagged bottom 2994', no plug. Spotted 3 more 25 sx plugs (total 75 sx) @ 2994'. WOC 2 hrs between plugs. Pulled tbg.
- 3/3/76 Dropped wiper plug in csg pushed plug to 2994'. Spotted 2-25 sx plugs. WOC 2 hrs. between plugs. Pulled tbg, rec. rubber plug on tbg. Ran tbg.
- 3/4/76 Lubricated in 160 gals sand down tbg, got 20' fill 2994'-2974'. Spotted 25 sx plug @ 2974'. WOC 2 hrs., tagged plug w/wireline @ 2934' (40' plug).
- 3/5/76 Spotted 25 sx plug 2934'. Hole loaded & circ. while displacing cement. Left 12 jts H-40 in hole (unscrewed). Ran wireline meas. & tagged top of cement 2692'. (242' plug). RU csg jacks.
- 3/6/76 Shot csg @ 1303' & 1261'. Rec. 27 jts 5½, 17#/ft J-55 csg (1264.67'). Ran tbg displaced hole above bottom plug w/9.5#/gal mud. Spotted 20 sx plug 1311'-1211'. Spotted 30 sx plug 348'-246'. Spotted 10 sx plug @ surface with drift marker.

PLUGGED AND ABANDONED 3-6-76.

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

General Superintendent

DATE

3-12-76

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

RECEIVED
MAR 15 1976
U.S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

See Instructions on Reverse Side

RECEIVED

MAR 11 1977

RECEIVED

ARTS & CRAFTS OFFICE

O.C.O.

MAR 9 1977

RECEIVED