

UNITED STATES OF AMERICA
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-03844

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injection Well		7. UNIT AGREEMENT NAME ROCK QUEEN UNIT	
2. NAME OF OPERATOR GREAT WESTERN DRILLING COMPANY		8. FARM OR LEASE NAME TRACT NO. 1	
3. ADDRESS OF OPERATOR P. O. BOX 1659 MIDLAND TX 79701		9. WELL NO. -2	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 330' FNL & 1650' FEL, Sec. 27, T-13-S, R-31-E		10. FIELD AND POOL, OR WILDCAT CAPROCK QUEEN	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SECTION 27	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) DF 4422'		12. COUNTY OR PARISH CHAVES	
		13. STATE NEW MEXICO	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Request permission to plug and abandon well due to offset producers cutting high percentages of water, which is not economical to produce.

Proposed plugging procedure is as follows: Note - mud laden fluid will be used between all plugs.

- (1) 100' cement plug @ bottom
- (2) 100' cement plug @ stub of production casing cut
- (3) 100' cement plug @ surface casing shoe
- (4) 10 sx cement plug @ surface
- (5) Steel marker, 4" dia., set in concrete w/4' above GL with lease name, well No., location, unit letter, section, township and range.

Notice will be given when final cleanup has ~~been~~ been made and location is ready for inspection.

Proposed plugging date is Dec., 1975.

RECEIVED

OCT 14 1975

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO


18. I hereby certify that the foregoing is true and correct

SIGNED L. H. Beckwith TITLE General Superintendent DATE 10-8-75

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:



*See Instructions on Reverse Side