16.

## NI.M. O. C. G. GOPY

UNITED STATES DEPARTMEN OF THE INTERIOR (Other Instructions of the Interior Verse side)

SUBMIT IN TRIPLICATE.

5.	LEASE	DESIGNA	MION	AND	SERIAL	NO.

GEOLOGICAL SURVEY							
SUNDRY NOTICES AND REPORTS	ON WELLS						
Alt. f and f a manner of a to doll on to double or blue	hook to a different recorn to						

(Do not use this form Use	for proposals to drill or to de "APPLICATION FOR PERMIT	epen or plug back to a different reservoir for such proposals.)		
1. OIL GAS WELL WELL	OTHER WATER INJECTION	ON WELL	7. UNIT AGREEMENT NA ROCK QUEEN UN	1.1
2. NAME OF OPERATOR			8. FARM OR LEASE NAM	
GREAT WESTERN DR	ILLING COMPANY	30-005-00892	TRACT NO. 3	-
3. ADDRESS OF OPERATOR			9. WELL NO.	
P. O. BOX 1659	10. FIELD AND POOL, OR WILDCAT CAPROCK QUEEN			
4. LOCATION OF WELL (Report See also space 17 below.) At surface				
UNIT LETTER F			11. SEC., T., R., M., OR B SUEVEY OR AREA	LK. AND
1650'FNL 2310'FWL,	Sec. 27, T-13-S,	R-31-E	SECTION 27	
14. PERMIT NO.	15. ELEVATIONS (SI	how whether DF, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE
	DF 4	.4281	CHAVES	NEW MEXICO

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE	-	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON*		WATER SHUT-OFF  PRACTURE TREATMENT SHOOTING OR ACIDIZING	REPAIRING WELL ALTERING CASING ABANDONMENT*	xx
REPAIR WELL (Other)	il	CHANGE PLANS		(Other) (Note: Report results of mult Completion or Recompletion Re	dple completion on Well	-

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

USGSSnotified 24 hrs. prior to setting bottom plug.

3/8/76 Ru csg pullers. Ran tbg & tagged B @ 2995'. Spotted 25 sx plug @ 2995'.

3/9/76 Ran wireline, tagged plug 2836'(159'). Loaded hole OK but went on vacuum. Spotted 25 sx plug 2836'. Hole loaded. Pulled tbg Ran wireline & tagged plug @ 2593'(243' plug). RU csg jacks.

3/10/76 Stretched & shot csg 1368'. Rec. 43 jts  $5\frac{1}{2}$ " J-55 csg (1377'). Ran tbg. & displaced hole above bottom plug w/9½#/gal mud. Spotted 20 sx plug 1418'-Spotted 30 sx plug 336'-234'. Spotted 10 sx plug at surface with dry hole marker.

PLUGGED AND ABANDONED 3-10-76

RECEIVED MAR 1 5 1976 U. S. GEOLOGICAL SURVEY ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct		· · ·		 	
SIGNED Show Signed Control			Superinter	DATE _	3-12-76
(This space for Federal or Stirte office.use)  APPROVED BY  CONDITIONS OF APPROVAL, IF ANY:	TITLE _			 DATE	

\*See Instructions on Reverse Side

D. D. D.

TTET & MAM

BECEINED