

COPIES RECEIVED	
DISTRIBUTION	
FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.  
**B-8822**

## SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>30-005-00916</u>		7. Unit Agreement Name
2. Name of Operator <b>Weldon S. Guest &amp; I. J. Wolfson</b>		8. Farm or Lease Name <b>Drickey</b> <b>Queen Sand Unit Tr 15</b>
3. Address of Operator <b>c/o Oil Reports &amp; Gas Services, Inc., Box 763, Hobbs, N. M. 88240</b>		9. Well No. <b>3</b>
4. Location of Well UNIT LETTER <b>I</b> <b>1986</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM <b>East</b> THE <b>35</b> LINE, SECTION <b>13 S</b> TOWNSHIP <b>31 B</b> RANGE <b>31 B</b> NMPM.		10. Field and Pool, or Wildcat <b>Cuprock Queen</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4413</b>		12. County <b>Chaves</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Subject well plugged and abandoned 10/23/73 as follows:**

Set cast iron bridge plug @ 2900 & capped with 5 sacks cement  
Shot & Pulled 5 1/2" casing from 2015  
Spotted plug from 2050 to 1950 with 30 sacks  
Spotted plug from 1500 to 1400 with 30 sacks  
Spotted plug from 300 to 200 with 30 sacks  
Set 10 sack plug at surface with regulation marker.  
10.1# mud (visc. 32) between all plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Weldon S. Guest</u>	TITLE <b>Agent</b>	DATE <b>10/24/73</b>
APPROVED BY <u>John W. Ryan</u>	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		