

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-521
7. Unit Agreement Name
8. Farm or Lease Name Drickey Queen Sand Unit Tr 28
9. Well No. 1
10. Field and Pool, or Wildcat Caprock Queen
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Injection Well
2. Name of Operator Weldon S. Guest & I. J. Wolfson
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, N.M.
4. Location of Well UNIT LETTER N , 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 35 TOWNSHIP 13 S RANGE 31 E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4413

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

It is proposed to plug as follows:

Set cast iron bridgeplug @ 3000 & cap with 3 sacks cement.
Cut & pull 5 1/2" casing from 2000.
Spot 100' plug across casing stub.
Spot 100' plug across top of salt @ 1500.
Set 100' plug across 13 3/8" casing shoe at 314.
10 sacks at surface with regulation marker.
Mud between all plugs.
Location to be cleaned & levelled.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Hermann Halkes* TITLE Agent DATE 10/18/73

APPROVED BY TITLE DATE
CONDITIONS OF APPROVAL, IF ANY: