TRIBUTION		Form C-103
1		Supersedes Old
YTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE OPERATOR		State X Fee.
O' ERATOR	30-005-00950	5. State Oil & Gas Lease No. B-6401
SU	NDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FO USE "APPI	NDRY NOTICES AND REPORTS ON WELLS R PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. LICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
l.		7. Unit Agreement Name
2. Name of Operator	OTHER- P&A	
Weldon S. Quest &	I. J. Walfnam	8. Farm or Lease Name Dricks
3. Address of Operator	. 20 00 0012000	Queen Sand Unit ir 38
c/o Oil Reports & Ga	s Services, Inc., Box 763, Hobbs, New Mexico	9. Well No.
4. Location of Well	The state of the s	10. Field and Pool, or Wildcat
UNIT LETTER	1830 FEET FROM THE South LINE AND 660 FEET FR	Cantook Ouean
,		THE THE THE THE MOST
THE WEST LINE, S	ECTION 2 TOWNSHIP 14 S RANGE 51 E NME	
mmmmm		
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
16.	4385 QR	Chaves \\\\\\\
Une.	ck Appropriate Box To Indicate Nature of Notice, Report or (
NOTICE	SUBSEQUE	NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	ALTERING CASING
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
	OTHER Re-enter & Co	alvage casing x
OTHER		
17. Describe Proposed or Complete work) SEE RULE 1103.	d Operations (Clearly state all pertinent details, and give pertinent dates, includi	ing estimated date of starting any proposea
Re-enter an Spotted 100 Spotted 100 Set 10 mack	d shot off 5 1/2" casing at 998, plug 998 to 1098 with 30 sacks. plug 275 to 375 with 30 sacks. plug at surface with regulation marker. prisc. 32) between all plugs.	ing estimated date of starting any proposed
Re-enter an Spotted 100 Spotted 100 Set 10 sack 10.1# mud (Werk comple	d shot off 5 1/2" casing at 998, plug 998 to 1098 with 30 sacks. plug 275 to 375 with 30 sacks. plug at surface with regulation marker. prisc. 32) between all plugs.	ing estimated date of starting any proposed
Re-enter an Spotted 100 Spotted 100 Set 10 sack 10.1# mid (Work comple)	ishot off 5 1/2" casing at 998, plug 998 to 1098 with 30 sacks. plug 275 to 375 with 30 sacks. plug at surface with regulation marker. risc. 32) between all plugs. to 11/1/73.	DATE 11/5/73
Re-enter an Spotted 100 Spotted 100 Set 10 sack 10.1# mid (Work comple)	d shot off 5 1/2" casing at 998, plug 998 to 1098 with 30 sacks. plug 275 to 375 with 30 sacks. plug at surface with regulation marker. risc. 32) between all plugs. to 11/1/73. donabove is true and complete to the best of my knowledge and belief. Agent	DATE 11/5/73