NO. OF COPIES RE						
					Fa	orm C-103
DISTRIBUTI	ON				Si	upersedes Old
SANTA FE			EXICO OIL CON	SERVATION COMMISSION		-102 and C-103 ffective 1-1-65
FILE					L.	Hective 1-1-65
U.S.G.S.					5a. In	dicate Type of Lease
LAND OFFICE						ate X Fee
OPERATOR						te Oil & Gas Lease No.
					0.010	E-7661
	SUND	RY NOTICES AND				
(DO NOT US	E THIS FORM FOR PA USE "APPLICA	TION FOR PERMIT - " (TO DEEPEN OR PLUG	WELLS BACK TO A DIFFERENT RESERVOIR CH PROPOSALS.)		
·				CH PROPUSALS.)		it Agreement Name
OIL	GAS WELL	OTHER- Wate	r Injection		/. 011	
Name of Operator			<u> </u>		0 Em	D.Q.S.U.
Cit	les Service	011 Company			18,10	
Address of Opera	tor					Tract 40
Box	69 - Hobbs	, New Mexico	88240		9. Wel	li No.
Location of Well	03 110003	, NEW FIEXT CO	00240			I
	N O	00	•		10. Fi	eld and Pool, or Wildcat
UNIT LETTER	<u> </u>	FEET FROM	M THE SOUTH	LINE AND 1650 F	EET FROM	Caprock Queen
Maa	•	•			7//	
THE	LINE, SECT	ION Z 1	TOWNSHIP 145	RANGE 31E	NMPM.	
mmm	mmm					
//////////	//////////			DF, RT, GR, etc.)	12. Co	ounty AIIIIII
			4404			Chaves
	Check	Appropriate Box	To Indicate N	ature of Notice, Report	t or Other Da	ta
	NOTICE OF I	NTENTION TO:		SUBSE	QUENT REPO	
						DRT OF:
PERFORM REMEDIAL V						
		PLUG	S AND ABANDON	REMEDIAL WORK		
EMPORARILY ABAND		PLUG	S AND ABANDON	REMEDIAL WORK		ALTERING CASING
				COMMENCE DRILLING OPNS.		ALTERING CASING
			G AND ABANDON	COMMENCE DRILLING OPNS. Casing test and cement Job		
				COMMENCE DRILLING OPNS.		
OTHER		CHAN	NGE PLANS	COMMENCE DRILLING OPNS. Casing test and cement JQB Other		PLUG AND ABANDONMENT
OTHER		CHAN	NGE PLANS	COMMENCE DRILLING OPNS. Casing test and cement JQB Other	ncluding estimate	PLUG AND ABANDONMENT
ULL OR ALTER CASIN		CHAN	NGE PLANS	COMMENCE DRILLING OPNS. Casing test and cement Job	ncluding estimate	PLUG AND ABANDONMENT
OTHER OTHER ?. Describe Propose work) SEE RULE	ed or Completed Of E 1 f03.	CHAN Derations (Clearly sta	IGE PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, i		PLUG AND ABANDONMENT
OTHER OTHER 7. Describe Propose work) SEE RULE	ed or Completed Of E 1 f03.	CHAN Derations (Clearly sta	IGE PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, i		PLUG AND ABANDONMENT
OTHER OTHER Describe Propose work) SEE RULE	ed or Completed O E 1 fos. above well	CHAN Derations (Clearly sta was plugged	te all pertinent deta and abandone	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, i ad in the following	manner:	PLUG AND ABANDONMENT
OTHER OTHER 7. Describe Propose work) SEE RULE	ed or Completed O E 1 fos. above well	CHAN Derations (Clearly sta was plugged	te all pertinent deta and abandone	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, i ad in the following	manner:	PLUG AND ABANDONMENT
ULL OR ALTER CASIN OTHER Describe Propose work) SEE RULE The 1.	ed or Completed O E 1 f03. above well Set a CI	CHAN Derations (Clearly sta was plugged Bridge Plug @	te all pertinent deta and abandon 2789 (7 ¹¹ se	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, i ails in the following at @ 3055 w/125 sxs)	PLUG AND ABANDONMENT
OTHER OTHER 7. Describe Propose work) SEE RULE The	ed or Completed O E 1 f03. above well Set a CI	CHAN Derations (Clearly sta was plugged Bridge Plug @	te all pertinent deta and abandon 2789 (7 ¹¹ se	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, i ails in the following at @ 3055 w/125 sxs)	PLUG AND ABANDONMENT
ULL OR ALTER CASIN OTHER Describe Propose work) SEE RULE The 1. 2.	ed or Completed Op et if 03. above well Set a CI i Set a 25 s	CHAN Derations (Clearly sta was plugged Bridge Plug @ sack cement p	and abandone 2789 (7 ¹¹ so lug on top o	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, i ad in the following)	PLUG AND ABANDONMENT
ULL OR ALTER CASIN OTHER Describe Propose work) SEE RULE The 1.	ed or Completed Op et if 03. above well Set a CI i Set a 25 s	CHAN Derations (Clearly sta was plugged Bridge Plug @	and abandone 2789 (7 ¹¹ so lug on top o	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, i ails in the following at @ 3055 w/125 sxs)	PLUG AND ABANDONMENT
ULL OR ALTER CASIN OTHER Describe Propose work) SEE RULE The 1. 2. 3.	ed or Completed Op et if 03. above well Set a CI i Set a 25 s	CHAN Derations (Clearly sta was plugged Bridge Plug @ sack cement p	and abandone 2789 (7 ¹¹ so lug on top o	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates, i ails in the following at @ 3055 w/125 sxs)	PLUG AND ABANDONMENT
OTHER OTHER Describe Propose work) SEE RULE The 1. 2.	ed or Completed O ed or Completed O E 1 f03. above well Set a CI Set a 25 Loaded ho Set a IO	chan perations (Clearly sta was plugged Bridge Plug @ Back cement p le with mud f Back cement st	and abandone 2789 (7 ¹¹ so lug on top o luid.	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER ails, and give pertinent dates, i ad in the following at @ 3055 w/125 sxs of bridge plug @ 27 @ 30-0 with a 4" m	manner:) 89-2664.	PLUG AND ABANDONMENT
ULL OR ALTER CASIN OTHER Describe Propose work) SEE RULE The 1. 2. 3.	ed or Completed O ed or Completed O E 1 f03. above well Set a CI Set a 25 Loaded ho Set a IO	chan perations (Clearly sta was plugged Bridge Plug @ Back cement p le with mud f Back cement st	and abandone 2789 (7 ¹¹ so lug on top o luid.	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER ails, and give pertinent dates, i ad in the following at @ 3055 w/125 sxs of bridge plug @ 27 @ 30-0 with a 4" m	manner:) 89-2664.	PLUG AND ABANDONMENT
ULL OR ALTER CASIN OTHER Describe Propose work) SEE RULE The 1. 2. 3.	ed or Completed O ed or Completed O E 1 f03. above well Set a CI Set a 25 Loaded ho Set a IO	chan perations (Clearly sta was plugged Bridge Plug @ Back cement p le with mud f Back cement st	and abandone 2789 (7 ¹¹ so lug on top o luid.	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER ails, and give pertinent dates, i ad in the following at @ 3055 w/125 sxs of bridge plug @ 27	manner:) 89-2664.	PLUG AND ABANDONMENT
OTHER OTHER Describe Propose work) SEE RULE The 1. 2. 3. 4.	ed or Completed O ed or Completed O E 1103. above well Set a CI Set a 25 Loaded ho Set a 10 4' above 1	chan berations (Clearly sta was plugged Bridge Plug @ sack cement p le with mud f sack cement so the surface to	and abandone 2789 (7 ¹¹ so lug on top o luid. urface plug o designate	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER ails, and give pertinent dates, i ad in the following et @ 3055 w/125 sxs of bridge plug @ 27 @ 30-0 with a 4" m a P & A location.	manner:) 89-2664. arker exte	PLUG AND ABANDONMENT
7. Describe Propose work) SEE RULE The 1. 2. 3.	ed or Completed O ed or Completed O E 1f03. above well Set a CI Set a 25 Loaded ho Set a 10 4' above Location i	CHAN Derations (Clearly sta was plugged Bridge Plug @ Back cement p ie with mud f Back cement so the surface to has been clear	and abandone 2789 (7 ¹¹ so lug on top o luid. urface plug o designate	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER ails, and give pertinent dates, i ad in the following at @ 3055 w/125 sxs of bridge plug @ 27 @ 30-0 with a 4" m	manner:) 89-2664. arker exte	PLUG AND ABANDONMENT
OTHER OTHER Describe Propose work) SEE RULE The 1. 2. 3. 4.	ed or Completed O ed or Completed O E 1f03. above well Set a CI Set a 25 Loaded ho Set a 10 4' above Location i	chan berations (Clearly sta was plugged Bridge Plug @ sack cement p le with mud f sack cement so the surface to	and abandone 2789 (7 ¹¹ so lug on top o luid. urface plug o designate	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER ails, and give pertinent dates, i ad in the following et @ 3055 w/125 sxs of bridge plug @ 27 @ 30-0 with a 4" m a P & A location.	manner:) 89-2664. arker exte	PLUG AND ABANDONMENT
OTHER OTHER Describe Propose work) SEE RULE The 1. 2. 3. 4.	ed or Completed O ed or Completed O E 1f03. above well Set a CI Set a 25 Loaded ho Set a 10 4' above Location i	CHAN Derations (Clearly sta was plugged Bridge Plug @ Back cement p ie with mud f Back cement so the surface to has been clear	and abandone 2789 (7 ¹¹ so lug on top o luid. urface plug o designate	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER ails, and give pertinent dates, i ad in the following et @ 3055 w/125 sxs of bridge plug @ 27 @ 30-0 with a 4" m a P & A location.	manner:) 89-2664. arker exte	PLUG AND ABANDONMENT
OTHER Describe Propose work) SEE RULE 1. 2. 3. 4.	ed or Completed O ed or Completed O E 1f03. above well Set a CI Set a 25 Loaded ho Set a 10 4' above Location i	CHAN Derations (Clearly sta was plugged Bridge Plug @ Back cement p ie with mud f Back cement so the surface to has been clear	and abandone 2789 (7 ¹¹ so lug on top o luid. urface plug o designate	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER ails, and give pertinent dates, i ad in the following et @ 3055 w/125 sxs of bridge plug @ 27 @ 30-0 with a 4" m a P & A location.	manner:) 89-2664. arker exte	PLUG AND ABANDONMENT
OTHER OTHER Describe Propose work) SEE RULE The 1. 2. 3. 4.	ed or Completed O ed or Completed O E 1f03. above well Set a CI Set a 25 Loaded ho Set a 10 4' above Location i	CHAN Derations (Clearly sta was plugged Bridge Plug @ Back cement p ie with mud f Back cement so the surface to has been clear	and abandone 2789 (7 ¹¹ so lug on top o luid. urface plug o designate	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER ails, and give pertinent dates, i ad in the following et @ 3055 w/125 sxs of bridge plug @ 27 @ 30-0 with a 4" m a P & A location.	manner:) 89-2664. arker exte	PLUG AND ABANDONMENT
OTHER Describe Propose work) SEE RULE 1. 2. 3. 4.	ed or Completed O ed or Completed O E 1f03. above well Set a CI Set a 25 Loaded ho Set a 10 4' above Location i	CHAN Derations (Clearly sta was plugged Bridge Plug @ Back cement p ie with mud f Back cement so the surface to has been clear	and abandone 2789 (7 ¹¹ so lug on top o luid. urface plug o designate	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER ails, and give pertinent dates, i ad in the following et @ 3055 w/125 sxs of bridge plug @ 27 @ 30-0 with a 4" m a P & A location.	manner:) 89-2664. arker exte	PLUG AND ABANDONMENT
OTHER OTHER Describe Propose work) SEE RULE 1. 2. 3. 4. 5.	ed or Completed O ed or Completed O E 1f03. above well Set a Ci i Set a 25 s Loaded ho Set a i0 n 4' above s Location i for final	berations (Clearly sta was plugged Bridge Plug @ sack cement p le with mud f sack cement so the surface to has been clear inspection.	and abandone and abandone 2789 (7 ¹¹ so lug on top o luid. urface plug o designate red of all o	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER ails, and give pertinent dates, i ad in the following et @ 3055 w/125 sxs of bridge plug @ 27 @ 30-0 with a 4" m a P & A location. lebris and equipmen	manner:) 89-2664. arker exte	PLUG AND ABANDONMENT
OTHER OTHER Describe Propose work) SEE RULE 1. 2. 3. 4. 5.	ed or Completed O ed or Completed O E 1103. above well Set a CI I Set a 25 s Loaded ho Set a 10 f 4' above Location i for final	chan berations (Clearly sta was plugged Bridge Plug @ sack cement p ie with mud f the surface to has been clear inspection.	and abandone and abandone 2789 (7 ¹¹ so lug on top o luid. urface plug o designate red of all o	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER ails, and give pertinent dates, i ad in the following et @ 3055 w/125 sxs of bridge plug @ 27 @ 30-0 with a 4" m a P & A location.	manner:) 89-2664. arker exte	PLUG AND ABANDONMENT
OTHER OTHER Describe Propose work) SEE RULE 1. 2. 3. 4. 5.	ed or Completed O ed or Completed O E 1103. above well Set a CI I Set a 25 s Loaded ho Set a 10 s 4' above Location i for final ORIGINAL SIG	CHAN Derations (Clearly sta was plugged Bridge Plug @ sack cement p le with mud f sack cement su the surface to has been clear inspection.	and abandone and abandone 2789 (7 ¹¹ so lug on top o luid. urface plug o designate red of all o	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER ails, and give pertinent dates, i ad in the following et @ 3055 w/125 sxs of bridge plug @ 27 @ 30-0 with a 4" m a P & A location. lebris and equipmen	manner:) 89-2664. arker exte	PLUG AND ABANDONMENT
OTHER . Describe Propose work) SEE RULE 1. 2. 3. 4. 5. I hereby certify the	ed or Completed O ed or Completed O E 1103. above well Set a CI I Set a 25 s Loaded ho Set a 10 f 4' above Location i for final	CHAN Derations (Clearly sta was plugged Bridge Plug @ sack cement p le with mud f sack cement su the surface to has been clear inspection.	AGE PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER ails, and give pertinent dates, i ad in the following et @ 3055 w/125 sxs of bridge plug @ 27 @ 30-0 with a 4" m a P & A location. lebris and equipmen	manner:) 89-2664. arker extent t and is re	PLUG AND ABANDONMENT
OTHER T. Describe Propose work) SEE RULE 1. 2. 3. 4. 5.	ed or Completed O ed or Completed O E 1103. above well Set a CI I Set a 25 s Loaded ho Set a 10 s 4' above Location i for final ORIGINAL SIG	CHAN Derations (Clearly sta was plugged Bridge Plug @ sack cement p le with mud f sack cement su the surface to has been clear inspection.	AGE PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER ails, and give pertinent dates, i ad in the following et @ 3055 w/125 sxs of bridge plug @ 27 @ 30-0 with a 4" m a P & A location. lebris and equipmen	manner:) 89-2664. arker extent t and is re	PLUG AND ABANDONMENT

CONDITIONE OF APPROVAL, IF ANY:

Geologist

TITLE

DEC 30 1970



> . .