

COPIES RECEIVED	
DISTRIBUTION	
FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form O-103  
Supersedes Old  
O-102 and O-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-10411</b>
7. Unit Agreement Name
8. Name of Lease Name <b>West Cap</b>
9. Well No. <b>Queen Sand Unit Tr 1</b>
10. Hole and Pool, or Wildcat <b>1</b>
11. Name and Pool, or Wildcat <b>Caprock Queen</b>
12. County <b>Chaves</b>

## SUNDY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM O-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Injection Well</b>
2. Name of Operator <b>Chavez Oil, Ltd</b>
3. Address of Operator <b>c/o Oil Reports &amp; Gas Services, Inc., Box 763, Hobbs, N.M. 88240</b>
4. Location of Well UNIT LETTER <b>H</b> <b>2310</b> FEET FROM THE <b>North</b> LINE AND <b>330</b> FEET FROM THE <b>East</b> LINE, SECTION <b>8</b> TOWNSHIP <b>14 S</b> RANGE <b>31 E</b> N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) <b>4104</b>

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug as follows:

Set cast iron bridgeplug @ 2500 & cap with 5 sacks cement.  
Cut & pull 5 1/2" casing from 2000.  
Spot 100' plug across casing stub.  
Spot 100' plug across top of salt @ 1500.  
Set 100' plug across 12 3/4" casing shoe @ 185.  
10 sacks at surface with regulation marker.  
Mud between all plugs.  
Location to be cleaned & levelled.

RECEIVED AT THE STATE OF NEW MEXICO  
OFFICE OF THE COMMISSIONER OF  
LANDS AND MINES FOR THE OILS  
AND GAS DIVISION

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Henry Haller TITLE Agent DATE 10/29/73

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: