


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **062486**
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 26, 1956

Federal Trigg Lease

Well No. **27-9** is located **1980** ft. from **N** line and **660** ft. from **E** line of sec. **9**

Sec. 9 **14-0** **31-E** **P.M.T.M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Caprock Queen **Chaves** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **4133** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

I propose to drill a 2750' Queen Sand test, using combination tools. I plan to drill to the 5 1/2" casing point with rotary, and drill in with cable tools.

8-5/8" surface pipe will be set at 90' with 50 sacks, which will circulate to the surface.

A 5 1/2" production string will be set in the Anhydrite cap overlying the Queen pay sand at approximately 2735' with 100 sacks.

All casing will be run and cemented under conditions approved by the U. S. Geological Survey.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **John H. Trigg**

Address **P. O. Box 5629**

Roswell, New Mexico

By _____


Title **Owner**

WELL LOCATION SURVEY PLAT

OPERATOR JOHN H TRIGG

LEASE FEDERAL TRIGG

WELL NO. 27-9



SEC. 9, TWP. 14 S., RGE. 31 E., N.M.P.M.

I HEREBY CERTIFY THAT THIS PLAT WAS MADE
FROM NOTES TAKEN IN THE FIELD BY ME AND
THAT THE SAME IS TRUE AND CORRECT TO THE
BEST OF MY KNOWLEDGE AND BELIEF.

John W West

JOHN W. WEST, PE & LS NO. 676 1-4-1956