

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

30-005-01038

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
D.Q.S.U.	
8. Farm or Lease Name	
Tract 45	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Caprock Queen	
12. County	
Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS	
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - Water Injection	
2. Name of Operator	
Cities Service Oil Company	
3. Address of Operator	
Box 69 - Hobbs, New Mexico 88240	
4. Location of Well	
UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM	
THE West LINE, SECTION 11 TOWNSHIP 14S RANGE 31E N.M.P.M.	
15. Elevation (Show whether DF, RT, GR, etc.)	
4519 DF	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above well was plugged and abandoned in the following manner:

1. Set a CI Bridge Plug @ 2960. (7" set @ 3049 w/1390 sx's)
2. Set a 25 sack cement plug on top of bridge plug @ 2960-2835.
3. Loaded hole with mud laden fluid.
4. Set a 10 sack cement surface plug @ 30-0 with a 4" marker extending 4' above the surface to designate a P & A location.
5. Location has been cleared of all debris and equipment and is ready for final inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Exp. 11/11/70</u>	TITLE District Manager	DATE 10/23/70
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Asst. Dir.</u>	DATE <u>11/10/70</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUN 28 1970

OIL CONSERVATION COM. I
HONOLULU, H. I.