

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <b>Water Injection</b>		7. Unit Agreement Name <b>D. Q. S. U.</b>
2. Name of Operator <b>Cities Service Oil Company</b>		8. Farm or Lease Name <b>Tract 47</b>
3. Address of Operator <b>Box 69, Hobbs, New Mexico 88240</b>		9. Well No. <b>4</b>
4. Location of Well UNIT LETTER <b>F</b> <b>1980</b> FEET FROM THE <b>North</b> LINE AND <b>1980</b> FEET FROM THE <b>West</b> LINE, SECTION <b>11</b> TOWNSHIP <b>14S</b> RANGE <b>31E</b> NMPM.		10. Field and Pool, or Wildcat <b>Caprock Queen</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4403 GR</b>		12. County <b>Chaves</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐



ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**We propose to plug and abandon the above well in the following manner:**

- 1. Set CI bridge plug in casing just above open hole. (7" set @ 3051' w/125 sxs)**
- 2. Set 25 sx cement plug on top of bridge plug.**
- 3. Load hole with mud laden fluid.**
- 4. Set 10 sack cement surface plug with a 4" dry hole marker.**
- 5. Clean location of all debris and equipment.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE <b>District Admin. Supervisor</b>	DATE <b>5/4/70</b>
APPROVED BY 	TITLE <b>DISTRICT ADMIN. SUPERVISOR</b>	DATE <b>MAY 1970</b>
CONDITIONS OF APPROVAL, IF ANY:		