

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>30-005-01071</u>		7. Unit Agreement Name <u>D.Q.S.U.</u>
2. Name of Operator <u>Weldon S. Guest & I. J. Wolfson</u>		8. Farm or Lease Name <u>Tract 41</u>
3. Address of Operator <u>c/o Hobbs Pipe & Supply, Box 2010, Hobbs, N. M.</u>		9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>C</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>16</u> TOWNSHIP <u>14S</u> RANGE <u>31E</u> NMPM.		10. Field and Pool, or Wildcat <u>Caprock Queen</u>
15. Elevation (Show whether DF, RT, GR, etc.)		12. County <u>Chaves</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>		COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 2502', with 5 sx cement on top.
2. Loaded hole w/mud-laden fluid.
3. Shot & recovered 700' of 7" production casing.
4. Spotted 40 sx plug in & out of surface casing, set @ 310'.
5. Set 10 sx top hole plug & erected 4" regulation marker.
6. Well was plugged and abandoned on 2/12/74.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. Saiter TITLE Agent DATE 4/10/74

APPROVED BY John W. Runyan TITLE Commissioner DATE 4/10/74

CONDITION OF APPROVAL, IF ANY: