

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Injection</u>		7. Unit Agreement Name
2. Name of Operator <u>Lewis B. Burleson, Inc.</u>		8. Farm or Lease Name <u>State D</u>
3. Address of Operator <u>P. O. Box 2479, Midland, Texas 79702</u>		9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>A</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>991, 1</u> FEET FROM THE <u>East</u> LINE, SECTION <u>27</u> TOWNSHIP <u>14-S</u> RANGE <u>31-E</u> NMPM.		10. Field and Pool, or Wildcat <u>East Caprock Queen</u>
15. Elevation (Show whether DF, RT, GR, etc.)		12. County <u>Chaves</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 5/14/86
1. Set CIBP 2850' Dump 35' cement on CIBP
 2. Casing would not test
 3. Set CIBP @ 210'. Test Casing
 4. Perf 4½" casing @ 200'
 5. Pump 50 sks. cement plug to establish circ between 4½ & 8-5/8" surface pipe.
 6. Pump 95 sks. cement to fill 4½" & between 4½ & 8-5/8 to ground surface.
 7. Install Marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wayne Jones TITLE Superintendent DATE 5/20/86

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE JUN 3 1986

CONDITIONS OF APPROVAL, IF ANY:

AF posted E

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Lewis B. Burleson, Inc.	8. Farm or Lease Name State D
3. Address of Operator Box 2479, Midland, TX 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>990</u> FEET FROM THE <u>north</u> LINE AND <u>991</u> / FEET FROM THE <u>east</u> LINE, SECTION <u>27</u> TOWNSHIP <u>14S</u> RANGE <u>31 E</u> NMPM.	10. Field and Pool, or Wildcat East Caprock Queen
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This is a shut-in well. It is proposed to plug and abandon as follows:

TD - 3130'
Surface Casing - 8-5/8" @ 200'
Production Casing - 4-1/2" @ 3128'

- Program: 1. Set CIBP above Queen perfs @ 3102-06' with 35' cement cap
2. Pressure test casing. If test ok, perf casing below surface casing shoe @ 200'. If casing does not hold, set CIBP @ 210' and test. Perforate holes @ 200' to spot 25 sack plug in 4-1/2" and between 4-1/2" and 8-5/8" surface casing.
3. Cap with 10 sacks cement.
4. Install marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wayne Jones TITLE Superintendent DATE 2-21-86

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAR 3 - 1986

CONDITIONS OF APPROVAL, IF ANY: