

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.
<b>Patent Land</b>

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Caprock Green Unit
3. Address of Operator	8. Farm or Lease Name
500 N. Maricopa - Midland, Texas	8. Caprock Green Unit
4. Location of Well	9. Well No.
UNIT LETTER <b>M</b> , <b>990</b> FEET FROM THE <b>S</b> LINE AND <b>990</b> FEET FROM THE <b>W</b> LINE, SECTION <b>28</b> , TOWNSHIP <b>14S</b> , RANGE <b>31 E</b> NMPM.	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
<b>OL 1226</b>	<b>Garza</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

### Plugging Procedures Below:

1. 8 5/8" @ 300' W/175 Sk.
2. 5 1/2" @ 3100' W/350 Sk.
3. Perf. @ 2895' - 2900'

- Plug #1 - 25 Sk. @ 3100'
- Plug #2 - 25 Sk. @ 5 1/2" Stub
- Plug #3 - 35 Sk. @ Base of Surface 300'
- Plug #4 - 5 Sk. @ Surface

Establish Dry Hole Marker

H. D. Glen, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <i>H. D. Glen</i>	TITLE <b>Agent for Union Oil of California</b>	DATE <b>July 13, 1971</b>

APPROVED BY <i>[Signature]</i>	TITLE <b>SUPERVISOR DISTRICT I</b>	DATE <b>JUL 15 1971</b>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUL 14 1971

OIL CONSERVATION COMM.  
HOUSTON, TEXAS