



LTR



Job separation sheet

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-3277

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO STILL OR TO FILL IN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - "M" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Temporarily Abandoned	7. Unit Agreement Name
2. Name of Operator Rapid Company, Inc.	8. Farm or Lease Name East Cap Queen Unit Tr35
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, New Mexico 88240	9. Well No. 1 4
4. Location of Well UNIT LETTER D 990 FEET FROM THE North LINE AND 330 FEET FROM THE West LINE, SECTION 34 TOWNSHIP 14 S RANGE 31 E N.M.P.M.	10. Field and Pool, or Wildcat Caprock Queen
15. Elevation (Show whether DF, RT, GR, etc.) 4427 G	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged & abandoned 2/11/75 as follows:

Set Cast iron bridge plug @ 3000 & cap with 35' cement
Cut & pulled 5 1/2" casing from 692'
Spotted 100' plug @ 692'
Spotted 100' plug across 8 5/8" casing shoe @ 282'
Set 10 sack plug at surface with regulation marker.
Mud between all plugs
Location cleared, levelled & ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u><i>John E. Ryan</i></u>	TITLE <u>Agent</u>	DATE <u>6/17/76</u>
APPROVED BY <u><i>John E. Ryan</i></u> Geologist	TITLE <u>Geologist</u>	DATE <u>6/17/76</u>
CONDITIONS OF APPROVAL, IF ANY:		