

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

AUG 9 8 15 AM '65

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-5364
7. Unit Agreement Name Eastcap Queen Unit
8. Farm or Lease Name Eastcap Queen
9. Well No. 32
10. Field and Pool, or Wildcat Caprock Field Caprock Queen Pool
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator Continental Oil Company
3. Address of Operator P. O. Box 460, Hobbs, New Mexico
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>34</u> TOWNSHIP <u>14</u> RANGE <u>31</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4407' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Re-enter & complete</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The following work was done on subject well in an attempt to re-enter and complete:

Before Workover - TD 3133, DF 11' AGL. DF Elev 4407
Csg pt 4 1/2" shot off @ 1979. Well plugged as follows:
3012-3033 W/12 sx 800-900 W/20 sx, 263-363 W/30 sx, 50-0
W/15 sx. Work done: Ran 6 1/2" bit and clean out to 245'.
Drld into junk & could not make hole. Re-placed cmt plug
0-50. Erected dry hole marker & filled cellar. After
workover - New plug @ 0-50', no change in other plugs.
Workover started 7-13-65, completed 7-14-65.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Robert Gault III TITLE Staff Supervisor DATE 8-4-65

APPROVED BY John W. Runyan TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:
NMOCC-5 SLO Partners 4 LPT