Direct of their micro ENERGY AND MINERALS DEPARTMENT

THE RESERVE OF THE PROPERTY OF			
·· we, or commen necesses			
DISTRIBUTION			
BANTA FE			
FILE	T		
U.S.O.S.			
LAND OFFICE			
OPPRATOR	1	_	

OIL CONSERVATION DIVISION

SANTA FE	SANTA FE, NEW MEXICO 87501	Revised 10-1-78
FILE	3	5a. Indicate Type of Lease
U.S.O.S.		State X Fee
DPERATOR	4	5, State Oil & Gas Lease No.
OF RAATON	J	1
C. M. D. F.	N. 107.056 AND DEPOSED A	E-7662
SUNDA	RY NOTICES AND REPORTS ON WELLS PROSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. TON FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)	
I.	ION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
WELL GAS WELL	OTHER. Injection	
Name of Operator	other. Injection	Caprock Queen
LEWIS B. BUI	RESON. INC.	State A
I. Address of Operator		9. Well No.
P.O. Box 2479	9 - Midland, TExas 79702	1
. Location of Well		10. Field and Pool, or Wildcat
	1980 South LINE AND 660	Caprock Queen
UNIT LETTER	FEET FROM THE LINE AND	TEET FROM THE
West	34 14 South 31 East	
THE LINE, SECTION	N TOWNSHIP RANGE	_ имрм. (((()))))))))))))))))))))))))))))))))
mmmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	13. Elevation (Snow whether DP, NT, OR, etc.)	Chaves
innininininininininininininininininini		
	Appropriate Box To Indicate Nature of Notice, Repor	t or Other Data
NOTICE OF IN	ITENTION TO: SUBSE	EQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABAHDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CABING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
 Describe Proposed or Completed Op work) SEE RULE 1103. 	erations (Clearly state all pertinent details, and give pertinent dates,	including estimated date of starting any proposed
Mbig is a shut in	11 M-/ 1 D //	
inis is a shut-in	well. Total Depth : 3082'	
	Surface Casing: 8-5/8" @ 2	
	Prod. Casing : 5-1/2" @ 3	3092 w/ 75 sx.
	Open hole @ 3092-3103'	
1 Dumm 10	01 -11	
I. Pump IU	0' plug above perfs in casing being	apprx. 25 sx. Then
tag plu	g •	
2. Set CIB	P @ 280'. Perforate squeeze holes @	280' to spot 45 sx plug
in 4-1/	2" and between 4-1/2' & 8-5/8" surfa	ce casing
		.oo oubling.
	h 10 sacks cement at surface.	
4. Install	marker fly at tip stall	
-11	106 July Com Con of The Mines of	10 Station in willing Hough
freeze	ZC THE C	OMMISSION MUST BE MOTIFIED 24
	HOUR!	S PRICE TO THE BITTINNING OF
	PLUGG	SING COLLATIONS FOR THE CHOS
I hereby certify that the information	bove is true and complete to the best of my knowledge and believ $B \mathcal{C}$	APPROVED.
41567	/ 5	
HED DION	ulasa rine President	DATE August 18, 1987
LEWIS B. BURLESON		
Orig. Signed by	`	ALIO 0 0 1007
Paul Kautz		AUG 2 0 1987
NOITIONS OF APPROVAL, IF ANY		

ANG 19 1940 occupance