ENERGY AND MINERALS DEPARTMENT

10. 00 COPIES ACCEIVED	Π	
DISTRIBUTION	1	
SANTA FE		
FILE		
U.1.G.1. **		
LAND OFFICE		
OPERATOR		

O CONSERVATION DIVISION	
DISTRIBUTION P. O. BOX 2088	Form C-103 ·
SANTA FE, NEW MEXICO 87501	Revised 10-1-78
rice	5a. Indicate Type of Lease
U.S.o.s. 33	
LAND OFFICE	
OPERATOR	5. State Oil 6 Gas Lease No.
	E 7662
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)	
	7. Unit Agreement Name
OIL X GAB	Caprock Queen
Name of Operator	8. Farm or Lease Name
LEWIS B. BURLESON, INC.	State A
Address of Operator	9. Well No.
P. O. Box 2479 - Midland, Texas 79702	#2
Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER N 660 FEET FROM THE SOUTH LINE AND 1980 FEET FR	Caprock Queen
THE West LINE, SECTION 34 TOWNSHIP 14 South ANGE 31 East NAME	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	Chaves ()
Check Appropriate Pay To Indicate Nature of Nation Papers of	Oak as Dana
Check Appropriate Box To Indicate Nature of Notice, Report or C	
NOTICE OF INTENTION TO: SUBSEQUE	NT REPORT OF:
REPORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
APORARILY ABANDON COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
L OR ALTER CABING CHANGE PLANS CASING TEST AND CEMENT JOB	
OTHER	
OTHER	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, include	ing estimated date of starting any proposed
work) SEE RULE 1103.	
 Spot 25 sks. Class C w/2% Ca Cl @ 3077'. 	
2. Tag plug @ 2940'.	
3. Circ. hole w/mud.	
4. Set CIBP @ 270'.	•
5. Perf squeeze holes @ 265'.	
6 Control 121 -1- Clare Control	
6. Cmt. w/131 sks. Class C to circ. cmt. in	and out of pipe.
7. Install marker.	
8. Cleaned location.	
This procedure was approved by your Hobbs office and	d your field man
who witnessed this operation.	
•	
·	

Lewis B. Burleson President OIL & GAS INSPECTOR JUT 5 1987