

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-4495
7. Unit Agreement Name
8. Farm or Lease Name New Mexico "BX" State
9. Well No. 5
10. Field and Pool, or Wildcat Chaverop S.A.
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Exxon Corporation 3. Address of Operator Box 1600, Midland, TX 79701 4. Location of Well UNIT LETTER M 662 FEET FROM THE South LINE AND 662 FEET FROM THE West LINE, SECTION 16 TOWNSHIP 8-S RANGE 33-E NMPM. 15. Elevator. (Show whether DF, RT, GR, etc.) 4394' D.F.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull rods, pump and tubing. Run tubing open ended and spot a 100' plug above the perforated interval from 4130'-4230' with 15²⁵ sxs cmt. Circ. hole with 9.5#/gal mud laden brine. Pull tbg. Cut 4½" csg. off above Bowen Csg. Bowl @ Approx. 3360'. Attempt to pull 4½" csg. If unable, stretch csg. to establish free point, cut and pull 4½" csg. Spot cmt. plugs through tbg. as follows:

- 100' plug below the Santa Rosa from 1400'-1500' with 35 sxs.
- 100' plug below the Ogallala and across the surface csg. shoe from 270'-370' with 35 sxs.
- 10' plug @ the surface.

Rig well head for abandonment and install marker.

100' plug @ 4½" stab
100' " " base seat

THE COMMISSION HAS REVIEWED THIS REPORT AND IT IS APPROVED 24
PLUG AND ABANDONMENT REPORT FOR THE C-103
TO BE APPROVED

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE SECTION HEAD DATE 12-11-74

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY: Dist. I, S...