

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O. C. C.
 NEW MEXICO OIL CONSERVATION COMMISSION
 Nov 28 8 16 AM '66

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Humble Oil & Refining Co.	3. Address of Operator Box 1600, Midland, Texas	4. Location of Well UNIT LETTER <u>M</u> <u>662</u> FEET FROM THE <u>south</u> LINE AND <u>662</u> FEET FROM THE <u>west</u> LINE, SECTION <u>16</u> TOWNSHIP <u>8-S</u> RANGE <u>33-E</u> NMPM.	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	5. State Oil & Gas Lease No. K-4495	7. Unit Agreement Name -	8. Farm or Lease Name New Mexico BX State	9. Well No. 5	10. Field and Pool, or Wildcat Chaveroo - S.A.	11. Elevation (Show whether DF, RT, GR, etc.) 4394 DF	12. County Chaves
--	--	--	---	--	--	-----------------------------	--	------------------	---	--	----------------------

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
 TEMPORARILY ABANDON ☐
 PULL OR ALTER CASING ☐
 OTHER ☐

PLUG AND ABANDON ☐
 CHANGE PLANS ☐
 OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒
 COMMENCE DRILLING OPNS. ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER ☐

ALTERING CASING ☐
 PLUG AND ABANDONMENT ☐
 OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled rods, pump & tb. Dowell acidized well as follows: 4200 gal Dowell Supr X, 4200 gal 3%, 250 gal jelled brine w/500# rock salt, 4200 gal Super X, 4200 gal 3%, 250 gal jelled brine w/500# rock salt, 4200 gal Super X and overflush w/4200 gal 3% at rate of 11.8 BPM, Max 2100 psi, SI pressure on vacuum. Swab test well. Reran tbg, rods & pump. Continue pump testing well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. L. Clemmer

TITLE Agent

DATE 11-23-66

APPROVED BY

TITLE

DATE 28 1966

CONDITIONS OF APPROVAL, IF ANY: