

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-4495

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Humble Oil & Refining Co.	8. Farm or Lease Name New Mexico BX State
3. Address of Operator Box 1600, Midland, Texas	9. Well No. 5
4. Location of Well UNIT LETTER <u>M</u> <u>662</u> FEET FROM THE <u>south</u> LINE AND <u>662</u> FEET FROM THE <u>West</u> LINE, SECTION <u>16</u> TOWNSHIP <u>8-S</u> RANGE <u>33E</u> NMPM.	10. Field and Pool, or Wildcat Chaveroo S.A.
15. Elevation (Show whether DF, RT, GR, etc.) 4394 DF	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Acidize well through perforations at 4231 to 4279' as follows:

- Stage 1. Inj. 4200 gal Dowell Super X acid plus additives.
2. Inj. 4200 gal 3% acid plus additives.
3. Inj 250 gal gelled, salt saturated brine wtr, containing 500# of rock salt.
4. Inj 4200 gal Dowell Super X acid plus additives.
5. Inj 4200 gal 3% acid plus additives.
6. Inj 250 gal gelled brine plug containing 500# of rock salt.
7. Inj 4200 gal Dowell Super X acid plus additives.
8. Overflush w/4200 gal 3% acid plus additives.
Swab well two days. Rerun pumping equipment & place on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. L. Clemmer TITLE Agent DATE 11-8-66

APPROVED BY _____ TITLE _____ DATE _____

REMARKS OF APPROVAL, IF ANY: