

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-4489
7. Unit Agreement Name
8. Farm or Lease Name State
9. Well No. 1
10. Field and Pool, or Wildcat Tobac
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Silver Monument Minerals, Inc.
3. Address of Operator Box 1476, Lovington, New Mexico
4. Location of Well UNIT LETTER E 1874 FEET FROM THE N LINE AND 554 FEET FROM THE W LINE, SECTION 28 TOWNSHIP 8-S RANGE 33-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4383 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Temporarily shut in on December 20, 1973.

1. Pull 1" tubing and hydraulic pump.
2. Pull 2 3/8" tubing.
3. Remove CIBP.
4. Re-run approximately 250' of additional tubing.
5. Acidize with 1000 gal.
6. Swab until all acid and acid water returned.
7. Re-run 1" string with additional 250' and hydraulic pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

Al Holder

TITLE **President**

DATE **1/10/74**

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: