

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name E-9089
2. Name of Operator EXXON CORPORATION	8. Farm or Lease Name NEW MEXICO "BW" STATE
3. Address of Operator P.O. Box 1600, MIDLAND, TEXAS 79702	9. Well No. 4
4. Location of Well UNIT LETTER <u>J</u> , 1988 FEET FROM THE <u>SOUTH</u> LINE AND 1997 FEET FROM THE <u>EAST</u> LINE, SECTION <u>16</u> TOWNSHIP <u>8 S</u> RANGE <u>33 E</u> NMPM.	10. Field and Pool, or Wildcat CHAUVERON SAN ANDRES
15. Elevation (Show whether DF, RT, GR, etc.) 4398 DF	12. County CHAVEZ

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐ CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPER. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1702.

1. MIRU. POH W/RODS AND PUMP. NU BOP TEST TO 2000 PSI. POH W/PRODUCTION TUBING.
2. PERF 4338-4366 W/29 SHOTS USING A 3 3/8" HOLLOW CARRIER JET CASING GUN W/PREMIUM CHARGES.
3. RIH W/TREATING PKR TO 4325' SET PKR AND BREAK PERF (4338-4366) DOWN WITH 3% KCL WTR.
4. ONCE PERF ARE BROKEN DOWN, AND W/PKR SET AT 4325' TEST FOR COMMUNICATION W/EXISTING PERF (4249-4319).
5. SWAB TEST 4338-4366 AND OBTAIN FORMATION WATER SAMPLE.
6. IF PRODUCTION IS NOT SATISFACTORY, ACIDIZE NEW PERF W/3000 GAL 15% NEHCL.
7. SWAB TO RECOVER LOAD AND TEST FOR PRODUCTIVITY. OBTAIN H2S ANALYSIS.
8. BASED ON WTR ANALYSIS, THE P1 AND P2 ZONES MIGHT BE COMMINGLED OR PRODUCED SEPARATELY.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie W. Seay TITLE SR ADMIN. DATE 2-23-84

Eddie W. Seay

Oil & Gas Inspector

APPROVED BY _____ TITLE _____ DATE FEB 28 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
FEB 24 1984
O. C. D.
ARTESIA, OFFICE

RECEIVED
FEB 27 1984
O. C. D.
HOBBS OFFICE