

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
E-9089

7. Unit Agreement Name

8. Farm or Lease Name
New Mexico "BW" State Battery 2

9. Well No.
6

10. Field and Pool, or Wildcat
Tobac Pennsylvania

12. County
Chaves

15. Elevation (Show whether DF, RT, GR, etc.)
4383' DF

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

12. County
Chaves

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER- ☐
2. Name of Operator Exxon Corporation
3. Address of Operator P.O. Box 1600, Midland, Texas 79701
4. Location of Well UNIT LETTER J 1985 FEET FROM THE South LINE AND 1997 FEET FROM THE East LINE, SECTION 21 TOWNSHIP 8-S RANGE 33-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.) 4383' DF

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedure 24 hr. notice

1. Pull rods and tubing.
2. Run cast iron bridge plug and set at 9000'. Dump 50' (5 sacks) cement plug on top of CI plug.
3. Free point and cut off 4 1/2" casing.
4. Circulate mud to surface through 4 1/2" casing. Mud will consist of 25 sx gel per 100 bbls.
5. Spot the following 100' Class H Cement plugs through the 4 1/2" casing. Pump all plugs down with mud.
 - A. 45 sx at about 7600', across 4 1/2" casing cut. +15 sx. per plug using casing
 - B. 45 sx, 7382-7282, Abo
 - C. 45 sx, 5016-4916, Glorieta
 - D. 45 sx, 3659-3559, across 7 5/8" casing shoe
6. Pull 4 1/2" casing
7. Free point and cut off and pull 7 5/8" casing
8. Run 2" tubing and spot Class C cement plugs as follows:
 - A. 60 sx, 1300-1900, across 7 5/8" casing cut and Rustler. B. 55 sx, 455-355, across 10 3/4" shoe. C. 103 sx, 0-10', surface.
9. Notify N.M.O.C.C. Rep to inspect location.

19. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Unit Head DATE 8-17-73

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____