NO OF CORIEC BECEIVE		
NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION NTA FE	NEW MEXICO OU CONSERVATION TO SERVE CO. C.	Supersedes Old
LE	MEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
	Aug ? High Mire	r
S.G.S.	-1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	5a. Indicate Type of Lease
PERATOR	<del>- </del>	State 🗶 Fee
		5. State Oil & Gas Lease No.
CLIMID	DDV NOTICES AND DETCE	E 10075
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE *APPLICATION FOR PERMIT -** (FORM C-101) FOR SUCH PROPOSALS.)		
OIL GAS WELL WELL		7. Unit Agreement Name
ame of Operator	OTHER-	8. Farm or Lease Name
Tom L. Ingram		
Address of Operator		9. Well No.
P. 0. Box 17	757 - Roswell, New Mexico	1
ocation of well		10. Field and Pool, or Wildcat
UNIT LETTER,	660 FEET FROM THE South LINE AND 1980 FEE	T FROM Wildcat
THELINE, SECT	TON 26 TOWNSHIP 8-5 RANGE 32-E	_ NMPM.
mmmmm	15. Elevation (Show whether DF, RT, GR, etc.)	
		12. County
	4421 DF	Chaves
Check	Appropriate Box To Indicate Nature of Notice, Report	or Other Data
NOTICE OF I		UENT REPORT OF:
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PORARILY ABANDON	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	7
PORARILY ABANDON		ALTERING CASING PLUG AND ABANDONMENT
PORARILY ABANDON . OR ALTER CASING	COMMENCE DRILLING OPNS.  CHANGE PLANS  CASING TEST AND CEMENT JQB	
Change Opera  rescribe Proposed or Completed Opera  rescribe RULE 1103.	COMMENCE DRILLING OPNS.  CASING TEST AND CEMENT JQB  OTHER  perations (Clearly state all pertinent details, and give pertinent dates, inc	PLUG AND ABANDONMENT
Change operator and the Bond on file.	COMMENCE DRILLING OPNS.  CHANGE PLANS  CASING TEST AND CEMENT JOB  OTHER	PLUG AND ABANDONMENT  Plug And Abandonment  Plug And Abandonment  Plug And Abandonment

ONDITIONS OF APPROVAL, IF ANY: