

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

ARTESIA OFFICE O. C. C.  
NEW MEXICO OIL CONSERVATION COMMISSION

JUL 5 8 14 AM '66

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>K-4274</b>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> <b>Dry Hole</b>	7. Unit Agreement Name
2. Name of Operator <b>Sunray Oil Company</b>	8. Farm or Lease Name <b>New Mexico "DD" St.</b>
3. Address of Operator <b>P.O. Box 1416, Roswell, New Mexico</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>A</b> , <b>660</b> FEET FROM THE <b>N</b> LINE AND <b>660</b> FEET FROM THE <b>E</b> LINE, SECTION <b>1</b> TOWNSHIP <b>9S</b> RANGE <b>31E</b> NMPM.	10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4408 DF</b>	12. County <b>Chaves</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		<b>Completed Report</b> <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Drilled 12 1/4" hole to 375'. Ran 8 5/8" OD csg to 373'. Cnt w/200 sxs reg. cnt. circ. cnt to surf. WOC 18 hrs. Test 1000# for 30 min. OK.
2. Drill 7 7/8" hole to 4109. Cut core #1 (4109-4168'). Cut Core #2 (4168-4224). Drill 7 7/8" hole to TD 4299.
3. Ran open hole logs.
4. Ran DP and laid 25 sxs. cnt. plugs 4300-4195, 25 sxs. 3380-3375, 25 sxs. 2200-2095, 25 sxs 1650-1545, 25 sxs 370-300 and 10 sxs plug at surface. Installed dry hole marker. P&A.

RECEIVED

JUL 1 1966

O. C. C.  
ARTESIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <b>B.F. Brawley</b>	TITLE <b>District Engineer</b>	DATE <b>6-30-66</b>
APPROVED BY <b>John W. Kuyper</b>	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		