Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, minerals and Natural Resources Department

Form C-103 Revised 1-1-89

CONDITIONS OF AFFROVAL, IF ANY:

OH CONSERVATION DIVISION

| P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 | -005-10465 |
|---|---|
| C . F. Mariae 97504 2088 | cate Type of Lease STATE XX FEE |
| SISTRICT III 6. State COO Rio Brazos Rd., Aztec, NM 87410 | e Oil & Gas Lease No. |
| SUNDRY NOTICES AND REPORTS ON WELLS | se Name or Unit Agreement Name |
| Type of Well: OIL GAS WELL X WELL OTHER KM | CHAVEROO SA UNIT |
| Name of Operator 8. We | II No. |
| KERR - MCGEE CORPORATION 34 | oi name or Wildcat |
| Address of Operator | VEROO (SAN ANDRES) |
| P.O. BOX 11050 MIDLAND, TEXAS 79702 CHA | - |
| Unit Letter D: 660 Feet From The NORTH Line and 660 | Feet From The WEST Line |
| Section 1 Township 8 SOUTH Range 33 EAST NMPM | CHAVES County |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | |
| 4339.6' GR | Other Date |
| Check Appropriate Box to Indicate Nature of Notice, Report, | OF OTHER DATA |
| NOTICE OF INTENTION TO: SUBSEQ | JENT REPORT OF: |
| RFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING |
| MPORARILY ABANDON CHANGE PLANS ' COMMENCE DRILLING OPNS | PLUG AND ABANDONMENT |
| JLL OR ALTER CASING CASING TEST AND CEMENT | JOB L |
| THER: Repair csg for conversion to inj well XX OTHER: | |
| 2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including esta | mated date of starting any proposed |
| wash SEE DITE 1103 to the second Innuary 3 199() | |
| - 1000 MIDH Pool TIH W/ 4 1/2" RPB & RTTS. SET RBP | ist. I have mark I and ha |
| w/ fresh water. Test RBP & tbg. to 3000 psig. POOH & set pkr @ 3000' ± & press test csg to I Will cont. to test to isolate hole(s). After hole and est. rate and press. After squeeze DC's & tbg. Drill out retainer and cement. Wi psig for 30". | 1000 psig above and below pkr hole is isolated, break down hob, will TIH w/ 3 7/8" bit, till pressure test csg. to 300 |
| w/ fresh water. Test RBP & tbg. to 3000 psig. POOH & set pkr @ 3000' ± & press test csg to I Will cont. to test to isolate hole(s). After hole and est. rate and press. After squeeze DC's & tbg. Drill out retainer and cement. Wi psig for 30". January 4, 1990 - GIH w/ DC Oil Tool Model AD-1 inj. pkr, SN & pkr setting depth. Set pkr. | 2 3/8" plastic coated tbg to |
| w/ fresh water. Test RBP & tbg. to 3000 psig. POOH & set pkr @ 3000' ± & press test csg to I Will cont. to test to isolate hole(s). After hole and est. rate and press. After squeeze DC's & tbg. Drill out retainer and cement. Wi psig for 30". January 4, 1990 - GIH w/ DC Oil Tool Model AD-1 inj. pkr, SN & pkr setting depth. Set pkr. | 2 3/8" plastic coated tbg to |
| w/ fresh water. Test RBP & tbg. to 3000 psig. POOH & set pkr @ 3000' ± & press test csg to I Will cont. to test to isolate hole(s). After hole and est. rate and press. After squeeze DC's & tbg. Drill out retainer and cement. Wi psig for 30". January 4, 1990 - GIH w/ DC Oil Tool Model AD-l inj. pkr, SN & pkr setting depth. Set pkr. January 5, 1990 - Load tbg-csg annulus w/ inhibited fluid. Tes | 2 3/8" plastic coated tbg to |
| w/ fresh water. Test RBP & tbg. to 3000 psig. POOH & set pkr @ 3000' + & press test csg to I Will cont. to test to isolate hole(s). After hole and est. rate and press. After squeeze DC's & tbg. Drill out retainer and cement. Wi psig for 30". January 4, 1990 - GIH w/ DC Oil Tool Model AD-1 inj. pkr, SN & pkr setting depth. Set pkr. January 5, 1990 - Load tbg-csg annulus w/ inhibited fluid. Tes | 2 3/8" plastic coated tbg to csg to 300 psig for 30 min |
| w/ fresh water. Test RBP & tbg. to 3000 psig. POOH & set pkr @ 3000' ± & press test csg to I Will cont. to test to isolate hole(s). After hole and est. rate and press. After squeeze DC's & tbg. Drill out retainer and cement. Wi psig for 30". January 4, 1990 - GIH w/ DC Oil Tool Model AD-l inj. pkr, SN & pkr setting depth. Set pkr. January 5, 1990 - Load tbg-csg annulus w/ inhibited fluid. Tes | 2 3/8" plastic coated tbg to cog to 300 psig for 30 min. |
| w/ fresh water. Test RBP & tbg. to 3000 psig. POOH & set pkr @ 3000' + & press test csg to I Will cont. to test to isolate hole(s). After hole and est. rate and press. After squeeze DC's & tbg. Drill out retainer and cement. Wi psig for 30". January 4, 1990 - GIH w/ DC Oil Tool Model AD-1 inj. pkr, SN & pkr setting depth. Set pkr. January 5, 1990 - Load tbg-csg annulus w/ inhibited fluid. Tes | 2 3/8" plastic coated tbg to csg to 300 psig for 30 min. |
| W/ fresh water. Test RBP & tbg. to 3000 psig. POOH & set pkr @ 3000' + & press test csg to will cont. to test to isolate hole(s). After hole and est. rate and press. After squeeze DC's & tbg. Drill out retainer and cement. Winsig for 30". January 4, 1990 - GIH w/ DC Oil Tool Model AD-1 inj. pkr, SN & pkr setting depth. Set pkr. January 5, 1990 - Load tbg-csg annulus w/ inhibited fluid. Test Thereby certify that the information above is true and complete to the best of my knowledge and belief. Signature A Manager Time Engineer | 2 3/8" plastic coated tbg to csg to 300 psig for 30 min |