

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

DEC 22 7 34 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- <u>Dry Hole</u>	7. Unit Agreement Name
2. Name of Operator PAN AMERICAN PETROLEUM CORPORATION	8. Farm or Lease Name CROSBY "C"
3. Address of Operator Box 68 Hobbs New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660'</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>8-S</u> RANGE <u>30-E</u> NMPM.	10. Field and Pool, or Wildcat CATO San Andres
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Graves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☒	OTHER <u>Completion Operations</u> ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD-3513, On 10-16-66, 4 1/2" OD 9.5" J-55 Casing was set at 3513 w/ 500 04 12% Gel + 300 sl neat. Would not test. Hole in casing above 1282'. Cut 4 1/2" @ 1282' and re-run and set on casing below @ 1282. Test casing 2000 psi. ok. Perforated intervals 3403-08, 19-39 w/250F + acidized w/ 2000 gal. Evaluated. 98% water. 5% oil. Set CI BP @ 3395. Perforated interval 3340-63 w/250F. Acidized w/ 2000 gal, 10,000 gal 28% HAc w/ 40000 gal Gel + 2" Sand Gel. Evaluated. Appx 96% water - 4% oil; Set bitumen at 3315 + squeezed w/ 200 sx. Perforated 3239-88 w/250F + acidized w/ 13,000 gal 28%. Evaluated. Last swab test on 11/13/66 made 98% water 2% oil. All pays evaluated - Dry Hole.

Propose to Plug and abandon as follows:
(over)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE Area Supt DATE 12-21-66

042-NMOCCL-H

1-NSW

APPROVED BY

1-SUSP

CONDITIONS OF APPROVAL, IF ANY:

1-RRV

TITLE _____ DATE _____

Plugging and abandonment Procedure

"Spot 25 sg cement plug 3315-3200 (Lugs 3239-3288)

Cut and pull 4 1/2" casing from free point.

Spot 20 sg cement plug in and out of 4 1/2" stub.

Spot 70 sg cement plug in and out of 8 7/8" CSA 458.

Spot 10 sg " " at surface and erect
P & A marker.

Make final cleanup and restore ground to
contour.