

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
DATE		
LE		
S.G.S.		
WFO OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR NOTICES TO ABANDON OR TO CARRY ON NEW CASE TO A DIFFERENT RESERVOIR.
USE MANIPULATIONS FOR NEW CASE OR PRODUCTION FOR THE SAME.)

OIL WELL ☐	GAS WELL ☐	OTHER ☐
-----------------------------------	-----------------------------------	--------------------------------

7. Unit Agreement Name

Name of Operator

8. Name of Lease Name

Address of Operator

9. Well No.

1300 WILCO BLDG, MIDLAND, TEXAS 79701

1

Location of Well

10. Field and Pool, or Wildcat

UNIT LETTER <u>H</u> : <u>1980</u> FEET FROM THE <u>N</u> LINE AND <u>660</u> FEET FROM

Cato

THE <u>E</u> LINE, SECTION <u>17</u> TOWNSHIP <u>8-S</u> RANGE <u>30-E</u> N.M.P.M.

11. Elevation (Show whether DP, RT, GR, etc.)

12. County

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

FORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
WELL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
OTHER ☐		OTHER ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Remove calcium sulfate scale.

1. Unseat pump.
2. Pump 500 gal. of C-Dex through tubing.
3. Reseat pump - shut in 4 hrs.
4. Pump down annulus w/formation water to displace C-Dex into formation.
5. Shut in 24 hrs.
6. Return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

By <u>Billie Hood</u>	TITLE <u>REGULATORY ANALYST</u>	DATE <u>9-8-81</u>
-----------------------	---------------------------------	--------------------