

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP!
(Other instructions
verse side)TE-
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

N. M. 025576

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

N. M. "X" Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Chaveroo

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

10 - 85 - 33E

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Sun Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 1861, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surfaceUnit Letter H, 1980' from the North Line and 660' from
the East Line, Section 10, Township 8-S, Range 33-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

2682 U.F.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

1. MIRU Pool Company 9-18-73
2. Pulled rods and tubing 9-18-73
3. Ran 2" tubing to 4400' and loaded hole with 9.5 lb. mud 9-19-73
4. Spotted 15 sacks cement, plug @ 4400' to 4220' Pulled out hole & weld on casing nipple. 9-19-73
5. Shot casing @ 2688, 2426 would not pull. 9-20-73
6. Pumped 50 sacks cement down 4" casing w/CATC plug to 2150' shut in 1 hour w/500 psi, 9-21-73
7. Shot casing @ 1708', could not pull casing 9-21-73
8. Squeered 50 sack cement with wiper plug. Displaced to 1600' 9-21-73
9. Shot casing @ 1021' pulled and laid down 32 joints 4" casing, 9-21-73
10. Ran tubing to 1070' and spotted 50 sacks cement, plug @ 1070' to 880'. 9-21-73
11. Spotted 35 sacks cement, plug @ 400' to 300' 9-21-73
12. Spotted 30 sacks cement in top 8-5/8" casing, weld cap on 8-5/8" casing and welded on permanent marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

Charles Gray

TITLE

Proration Clerk

DATE

10-15-73

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and data well site conditioned for final inspection looking to approval of the abandonment.