		$\left\{ \mathbf{v}_{i}^{\mathbf{r}}\right\} =\left\{ \mathbf{v}_{i}^{\mathbf{r}}\right\}$			
Form 9–331 (May 1963)	UN - 5D STATES		SUBMIT IN TRIP! TE		Form approved. Budget Burcau No. 42-R1424.
DEF		TME OF THE INTER	RIOR (Other instruction	re- 5.	LEASE DESIGNATION AND SERIAL NO.
		GEOLOGICAL SURVEY			NM 0554490
	-	DTICES AND REPORTS opesals to drill or to deeped or plus ACATION FOR PERMIT for such		6.	. IF INDIAN, ALLOTTEE OR THIBE NAME
1. OIL GAS OTHER					UNIT AGREEMENT NAME
2. NAME OF OPERATOR					. FARM OR LEASE NAME
Atlantic Richfield Company					Sinclair 208, Federal
3. ADDRESS OF OPERATOR					. WELL NO.
P. O. Box 1710, Hobbs, New ^M exico 88240					1
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 					0. FIELD AND POOL, OR WILDCAT Cato-San Andres
660' FNL	& 660' FEL	(Unit letter A)			1. SEC., T., E., M., OR BLK. AND SUBVEY OR ABEA Sec 20, T8S, R30E
14. PERMIT NO.		15. ELEVATIONS (Show whether	DF, RT, GR, etc.)		2. COUNTY OB PARISH 13. STATE
		4089' GR			Chaves N.M.
16.	Check	Appropriate Box To Indicate	Nature of Notice, Report, o	r Othe	er Data
NOTICE OF INTENTION TO: SUBSEQU					F LEPORT OF:
TEST WATER SI	HUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF		REPAIRING WELL
FRACTURE TREA	т	MULTIPLE COMPLETE	FRACTURE TREATMENT		ALTERING CASING
SHOOT OR ACID	(Z)D	ABANDON*	SHOOTING OR ACIDIZING		ABANDONMENT* X
REPAIR WELL		CHANGE PLANS	(Other)		
(Other)			(NOTE: Report resu Completion or Reco	ilts of mpletio	multiple completion on Well
17. DESCRIBE PROPOS	ED OR COMPLETED	OPERATIONS (Clearly state all pertin	ent details, and give pertinent da	tes, inc	luding estimated date of starting any

11. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Moved in and rigged up on 5/2/74. Set 20 sk cmt plug 3159-3400'. Circ well w/heavy mud. Cut $4\frac{1}{2}$ " csg @ 2075', recovered 65 jts & cut piece of $4\frac{1}{2}$ " csg. Set 40 sk cmt plug 1960-2090' across $4\frac{1}{2}$ " csg stub. Set 40 sk cmt plug 385-515' across 8-5/8" csg shoe. Set 10 sk cmt plug @ surface. Welded on plate, installed regulation marker. Clean & level location. Well P&A effective 5/6/74.

Your office will be notified by letter when location is ready for inspection.

RECEIVED

MAY - 91974

U. S. GEOLOGICAL SURVEY ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and SIGNED	Correct	DATE5/8/74
(This space for Every or State office use)		DATE
ACTING DISTRICT ENGINEER	*See Instructions on Reverse Side	