

5. LEASE DESIGNATION AND SERIAL NO.
NM 0461288

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

JUN 19 9 29 AM '67

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dryhole		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR Sunray DX Oil Company		8. FARM OR LEASE NAME New Mexico "Y" Federal	
3. ADDRESS OF OPERATOR P. O. Box 1416, Roswell, New Mexico		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FBL & 660' FBL of Section 35, T-9-S, R-31-E, Chaves County, New Mexico		10. FIELD AND POOL, OR WILDCAT Wildcat	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4245 DF	
12. COUNTY OR PARISH Chaves		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Spudded well 5-29-67. Drilled 12 1/4" hole to 377'. Ran 8 5/8", 24#, J-35 csg to 377'. Cnt w/250 sxs reg. 2X CaCl. Job complete 5-29-67. Circ 35 sxs to surface, WOC 18 hrs. Tested BOP & csg to 1000# for 30 min. OK.
2. Drilled 7 7/8" hole to 4250'. Ran Densilog, Focused and Minifocused open hole logs. Job complete 6-7-67.
3. Ran DST over interval 3960'-4250'. Recovered 426' muddy water and 1306' black brackish salt water. No oil or gas odors.
4. Prep to P&A.
5. Will lay cnt plugs as follows: 100 sxs 4250-3930'; 25 sxs 3330-3230'; 25 sxs 2890'-2790'; 25 sxs 427'-327' (in and out of base of 8 5/8"); 15 sxs at surface.
6. Will install dry hole marker and clear location.

18. I hereby certify that the foregoing is true and correct

SIGNED

John Hastings
John Hastings

TITLE

District Engineer

DATE

June 9, 1967

(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JUN 7 1967
Richard B. KRAHL
RICHARD B. KRAHL

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963 - O-685229

507-651