

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP DATE*
(Other instruction reverse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.
NM-0276225

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Shell Oil Company (Western Division)

3. ADDRESS OF OPERATOR

P. O. Box 1509, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface1980' FEL & 1980' FSL, Sec. 22, T-8-S, R-30-E,
MMPM, Chaves County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4160' DF

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Cato (San Andres)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Brown Federal9. WELL NO.
210. FIELD AND POOL, OR WILDCAT
Cato (San Andres)11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 22, T-8-S, R-30-E
MMPM12. COUNTY OR PARISH
Chaves13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pull rods, pump & tubing.
2. Premix 33,000 gallons, 9¢/gallon, gelled water. Mix w/Adomite Aqua, guar gum.
Use 1 gallon Adomite/1000 gallons gelled water. Frac as follows:
 - a. Pump 4000 gallons gelled water pad.
 - b. Pump 4000 gallons gelled water w/1 1/2¢/gallon 20-40 mesh sand. Drop 1-7/8" MCK ball sealer.
 - c. Pump 3000 gallons gelled water w/1 1/2¢/gallon 20-40 mesh sand. Drop 1 ball sealer.
 - d. Repeat step c 6 times (omit ball sealer on last stage). Total: 25,000 gallons gelled water w/1 1/2¢/gallon sand & 7 ball sealers.
 - e. Flush w/gelled water.
3. Run tubing, swab until no sand return.
4. Run rods & pump.
5. Place on production.

18. I hereby certify that the foregoing is true and correct

SIGNED Original Signed By
N. W. Harrison

N. W. Harrison

RECEIVED
DATE March 27, 1968

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

U. S. GEOLOGICAL SURVEY
POSWELL, NEW MEXICO

*See Instructions on Reverse Side

APR 2 1968

J. W. SUTHERLAND
DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.