

OIL CONSERVATION DIVISION

P. O. BOX 2086
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" FORM C-101 FOR SUCH PROPOSALS.

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator: ARCO Oil and Gas Company Division of Atlantic Richfield Company		8. Farm or Lease Name L. C. Harris
3. Address of Operator P. O. Box 1710, HOBBS, New Mexico 88240		9. Well No. 8
4. Location of Well UNIT LETTER 0 660 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 15 TOWNSHIP 8S RANGE 30E NMPM.		10. Field and Pool, or Whacat Cato San Andres
11. Elevation (Show whether DF, RT, GR, etc.) 4160' GR		12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Add Perfs Same Zone & Treat <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.


RU, install BOP & POH w/compl assy. Set CIBP @ 3350' & cap w/35' cmt. Run GR-CCL. Spot 50 gals 10% acetic acid 3200-50'. Perforate upper San Andres w/1 JS @ 3212, 13, 23, 25, 37, 38, 39, 40, 41, 42' = 10 .49" holes. RIH w/pkr, set pkr @ 3100'. Acidize perfs 3212-3242' w/5000 gals 28% NEA in 2 stages, flush to top perf w/wtr. Swab load and test. POH w/pkr. RIH w/compl assy & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Richard W. Lawrence TITLE Drlg. Engr. DATE 8/27/82

APPROVED BY _____ TITLE _____ DATE 1982

CONDITIONS OF APPROVAL, IF ANY:



ARCO Oil & Gas Company

Division of Atlantic Richfield Company

Blow Out Preventer Program

Lease Name L. C. Harris

Well No. 8

Location 660' FSL & 1980' FEL
Sec 15-8S-30E, Chaves County

BOP to be tested when installed on well and will be maintained in good working condition during drilling. All wellhead fittings to be of sufficient pressure to operate in a safe manner.