

NMOCC - ARTESIA
NMOCC - HOBBS
BLM - SANTA FE

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER DRY HOLE		5. LEASE DESIGNATION AND SERIAL NO. NM-041243	
2. NAME OF OPERATOR SOUTHWEST PRODUCTION CORPORATION		6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A	
3. ADDRESS OF OPERATOR P. O. BOX 936 - ROSWELL, NEW MEXICO 88201		7. UNIT AGREEMENT NAME N/A	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FWL - - Sec. 28 - T9S E R30E		8. FARM OR LEASE NAME AMERICAN FEDERAL	
14. PERMIT NO. N/A		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4075 GR		10. FIELD AND POOL, OR WILDCAT Wildcat	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 28 - T9S - R30E	
		12. COUNTY OR PARISH Chaves	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cut and pulled 2465' 4½" casing.
Set cement plug TD (3575') to 3400' (all perfs.)
Set cement plug 2500' to 2400' (Top 4½" csg.)
Set cement plug 1550' to 1450'.
Set cement plug 850' to 750'.
Set 30 foot cement plug at surface.
Mud used between plugs.
Set dry hole marker and cleaned location.
P & A 7/26/67.

RECEIVED

JAN 20 1969

O. C. C.
ARTESIA, OFFICE

U. S. GEOLOGICAL SURVEY
SANTA FE, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

WALTER CLEMENTS, JR.

TITLE

Manager

DATE

8/7/67

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

*See Instructions on Reverse Side